



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-11-08
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	6
Total items failed	7

MOT #16	2023-11-10 09:01
MOT test number	508771054036
Result	✓ Passed
Next expiry date	2024-11-10
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2023-11-10 09:01
MOT test number	978100264122
Result	✗ Failed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14	2022-11-10 14:05
MOT test number	674208826098
Result	✓ Passed

MOT #13	2022-11-10 08:14
MOT test number	692851972456
Result	✗ Failed
Fail	Offside Rear Hydraulic brake calliper leaking and braking performance affected (1.1.16 (b) (ii))

**MOT #12** 2021-11-11 12:59**MOT test number** 720626895467**Result** ✓ Passed**MOT #11** 2021-03-02 11:14**MOT test number** 401819300361**Result** ✓ Passed**MOT #10** 2021-03-02 09:18**MOT test number** 989769851309**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2020-03-04 12:24**MOT test number** 330205987007**Result** ✓ Passed**MOT #8** 2019-03-07 09:16**MOT test number** 930940346330**Result** ✓ Passed**MOT #7** 2019-03-05 09:32**MOT test number** 692610534561**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #6** 2018-03-01 16:27**MOT test number** 634779659059**Result** ✓ Passed**MOT #5** 2017-08-03 12:10**MOT test number** 525196206864**Result** ✓ Passed**Advice** Rear tyres perished**MOT #4** 2016-08-12 08:02**MOT test number** 633438190065**Result** ✓ Passed**MOT #3** 2015-08-13 08:50**MOT test number** 753836437624**Result** ✓ Passed**MOT #2** 2014-08-29 14:50**MOT test number** 246111644250**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-02-06 13:58**MOT test number** 596657334051**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YR11TXU
Plate since	2024-03-29
Current registration	YR11TXU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-14
Last registration	2023-11-10
Complete history	See info



Registration #1	2011-04-14	25 mi
Registration #2	2014-02-06	11.592 mi
Registration #3	2014-08-29	12.250 mi
Registration #4	2015-08-13	17.121 mi
Registration #5	2016-08-12	20.703 mi
Registration #6	2017-08-03	24.040 mi
Registration #7	2018-03-01	25.030 mi
Registration #8	2019-03-05	27.603 mi
Registration #9	2019-03-07	27.603 mi
Registration #10	2019-03-07	27.603 mi
Registration #11	2019-03-07	27.603 mi
Registration #12	2019-03-07	27.603 mi
Registration #13	2019-03-07	27.603 mi
Registration #14	2019-03-07	27.603 mi
Registration #15	2019-03-07	27.603 mi
Registration #16	2019-03-07	27.603 mi
Registration #17	2019-03-07	27.603 mi
Registration #18	2019-03-07	27.603 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1346 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1038586