



report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-22
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #16	2022-10-31 16:52
MOT test number	823355910378
Result	✓ Passed
Next expiry date	2023-11-07

MOT #15	2022-10-31 12:03
MOT test number	937988436988
Result	✗ Failed
<div><div>Fail</div>Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))</div> <div><div>Fail</div>Nearside Front Position lamp not working (4.2.1 (a) (ii))</div> <div><div>Fail</div>Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))</div> <div><div>Fail</div>Nearside Inner Vehicle structure is fractured and structural rigidity is significantly reduced (6.1.1 (a) (i))</div> <div><div>Fail</div>Nearside Stop lamp(s) not working (4.3.1 (a) (ii))</div> <div><div>Fail</div>Fuel system component leaking (6.1.3 (b) (i))</div>	

MOT #14	2021-11-08 09:09
MOT test number	189502785889
Result	✓ Passed
<div><div>Advice</div>Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div> <div><div>Advice</div>Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	

MOT #13	2020-11-04 10:32
MOT test number	490344467452
Result	✓ Passed

**MOT #12**

2020-11-03 08:43

MOT test number

310756640617

Result

✗ Failed

Fail

Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #11

2019-05-23 09:52

MOT test number

399129156098

Result

✓ Passed

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10

2018-06-06 09:08

MOT test number

869084872994

Result

✓ Passed

Advice

Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9

2017-04-05 16:23

MOT test number

515293018785

Result

✓ Passed

Advice

Offside Rear Nail in tyre

Advice

Nearside Rear Tyre worn close to the legal limit worn on inner edge (4.1.E.1)

**MOT #8**

2017-03-27 09:45

MOT test number

987002719548

Result

✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Parking brake lever has no reserve travel requires adjustment(shoes) (3.1.6b)
- Pass with rectification** Offside Front Headlamp aim too low level motor incorrectly fitted (1.8)
- Fail** Offside Front Tyre has ply or cords exposed inner edge (4.1.D.1b)
- Advice** Front Brake pad(s) wearing thin both sides around 3mm (3.5.1g)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Side repeater incorrect colour (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit worn badly on inner edge advise regular checks or change (4.1.E.1)
- Advice** Offside Rear Nail in tyre
- Fail** Offside front parking (secondary) brakes imbalanced far behind n/s application (3.7.B.6b)

MOT #7

2016-04-06 15:21

MOT test number

164370840854

Result

✓ Passed

MOT #6

2015-07-22 16:45

MOT test number

365993305414

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Rear seat belts not checked. Seats unavailable.
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #5** 2015-07-22 15:38**MOT test number** 467933305295**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Rear seat belts not checked. Seats unavailable.**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Front front brake binding (3.7.B.1)**MOT #4** 2014-01-09 11:41**MOT test number** 538079804044**Result** ✓ Passed**Notice** EML on**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2012-12-24 10:40**MOT test number** 717589652336**Result** ✓ Passed**MOT #2** 2012-01-04 09:13**MOT test number** 665124902052**Result** ✓ Passed**MOT #1** 2011-01-12 12:22**MOT test number** 527452211085**Result** ✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	WA57VFB
Plate since	2019-09-28
Current registration	WA57VFB
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-02-25
Last registration	2022-10-31
Complete history	See info



Registration #1	2008-02-25	25 mi
Registration #2	2011-01-12	29.768 mi
Registration #3	2012-01-04	30.850 mi
Registration #4	2012-12-24	36.827 mi
Registration #5	2014-01-09	53.348 mi
Registration #6	2015-07-22	73.385 mi
Registration #7	2015-07-22	73.392 mi
Registration #8	2016-04-06	79.101 mi
Registration #9	2017-03-27	88.483 mi
Registration #10	2018-03-27	95.377 mi
Registration #11	2019-03-27	95.377 mi
Registration #12	2020-03-27	95.377 mi
Registration #13	2021-03-27	95.377 mi
Registration #14	2022-03-27	95.377 mi
Registration #15	2023-03-27	95.377 mi
Registration #16	2024-03-27	95.377 mi
Registration #17	2025-03-27	95.377 mi
Registration #18	2026-03-27	95.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1657 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4EA6H26705