



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SPORT D V50
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-12-04
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #17	2023-11-13 15:52
MOT test number	527386152434
Result	✓ Passed
Next expiry date	2024-12-04

MOT #16	2023-11-13 15:52
MOT test number	604149110804
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15	2022-11-23 10:03
MOT test number	797628568800
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear cracks between treads both rear tyres
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2021-11-18 16:40
MOT test number	203899843172
Result	✓ Passed

**MOT #13** 2020-12-05 09:02**MOT test number** 840490833393**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2020-12-05 09:02**MOT test number** 226522158566**Result** ✗ Failed

**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2020-08-06 15:38**MOT test number** 148111082008**Result** ✓ Passed

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2018-07-25 11:10**MOT test number** 342508614593**Result** ✓ Passed

**MOT #9** 2017-07-22 08:57**MOT test number** 338607246401**Result** ✓ Passed**Advice** Nearside Rear tyre devoid of tread on inner edge**Advice** Offside Rear tyre devoid of tread on inner edge**MOT #8** 2016-07-14 13:41**MOT test number** 634417910883**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-07-14 13:41**MOT test number** 518205929625**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #6** 2015-07-18 09:25**MOT test number** 628019695170**Result** ✓ Passed**Notice** Both front tyres bald on inner shoulders**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Exhaust rear silencer outer skin deteriorated**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-07-23 10:18**MOT test number** 257734604253**Result** ✓ Passed



MOT #4	2013-07-26 08:39
MOT test number	739257903258
Result	✓ Passed

MOT #3	2013-07-20 10:57
MOT test number	738091303260
Result	✗ Failed
<div><div>Notice</div> Nail in inner shoulder of nearside rear tyre</div> <div><div>Fail</div> Offside Front coil spring broken (2.4.C.1a)</div> <div><div>Notice</div> Both front tyres scrubbed on shoulders</div> <div><div>Fail</div> Nearside Front coil spring broken (2.4.C.1a)</div>	

MOT #2	2012-07-12 09:56
MOT test number	157344892124
Result	✓ Passed

MOT #1	2011-07-13 09:49
MOT test number	637594191148
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
4 December 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	4 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-29
Last registration	2023-11-13
Complete history	<a href="#">See info</a>



Registration #1	2008-07-29	11 mi
Registration #2	2011-07-13	26.287 mi
Registration #3	2012-07-12	36.267 mi
Registration #4	2013-07-20	45.044 mi
Registration #5	2013-07-26	45.423 mi
Registration #6	2014-07-23	56.038 mi
Registration #7	2015-07-18	63.943 mi
Registration #8	2016-07-14	71.205 mi
Registration #9	2016-07-14	71.205 mi
Registration #10	2017-07-22	74.187 mi
Registration #11	2018-07-20	75.277 mi
Registration #12	2019-07-20	75.277 mi
Registration #13	2020-07-20	75.277 mi
Registration #14	2021-07-20	75.277 mi
Registration #15	2022-07-20	75.277 mi
Registration #16	2023-07-20	75.277 mi
Registration #17	2024-07-20	75.277 mi
Registration #18	2025-07-20	75.277 mi
Registration #19	2026-07-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	211142