



AV59HHB

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Black
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2024-05-25
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	16
Total items failed	4

MOT #12	2023-05-03 10:12
MOT test number	627207043283
Result	✓ Passed
Next expiry date	2024-05-25

MOT #11	2023-05-03 09:10
MOT test number	255245050075
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Registration plate insecure in front window and damaged (0.1 (a))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #10	2022-04-26 10:30
MOT test number	233301606990
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front fog light broken

**MOT #9** 2021-05-26 10:40**MOT test number** 989729774859**Result** ✓ Passed

- Advice** Emissions to clean to read
- Advice** Rear anti roll bar corrosion
- Advice** Sills covered and full under try fitted

MOT #8 2020-02-12 13:34**MOT test number** 630890891413**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-02-13 10:18**MOT test number** 932339086395**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Both rear tyres cracking on side walls
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #6 2017-09-12 08:58**MOT test number** 890969527526**Result** ✓ Passed

- Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2016-09-15 10:19**MOT test number** 891150957526**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2015-09-17 09:02**MOT test number** 959544457112**Result** ✓ Passed**MOT #3** 2014-09-18 09:42**MOT test number** 899971164268**Result** ✓ Passed**MOT #2** 2013-09-11 15:55**MOT test number** 326984453233**Result** ✓ Passed**MOT #1** 2012-09-24 12:13**MOT test number** 585648162294**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-26
Last registration	2023-05-03
Complete history	See info



Registration #1	2009-09-26	8 mi
Registration #2	2012-09-24	8.062 mi
Registration #3	2013-09-11	10.840 mi
Registration #4	2014-09-18	13.508 mi
Registration #5	2015-09-17	18.281 mi
Registration #6	2016-09-15	24.166 mi
Registration #7	2017-09-12	29.755 mi
Registration #8	2018-09-10	35.344 mi
Registration #9	2019-09-08	40.933 mi
Registration #10	2020-09-06	46.522 mi
Registration #11	2021-09-04	52.111 mi
Registration #12	2022-09-02	57.700 mi
Registration #13	2023-05-03	63.289 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C73512