



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT DDIS
Colour	Orange
Year of manufacture	2009
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-03
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-05
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	8

MOT #16	2023-07-04 13:13
MOT test number	609765101306
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-07-06 15:10
MOT test number	707806911258
Result	✓ Passed
Advice	Offside Rear Nail in tyre
Advice	N/s rear brake binding slightly
Advice	O/s rear tyre bald on outer edge
Advice	Fuel Pipe/s corroded
Advice	Nearside Rear tyre balding on inner edge and cracking

**MOT #14**

2022-06-30 15:11

MOT test number

685542096162

Result**✗ Failed****Advice** Offside Rear Nail in tyre**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear tyre balding on inner edge and cracking**Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))**Advice** Fuel Pipe/s corroded**Fail** Nearside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** N/s rear brake binding slightly**Advice** O/s rear tyre bald on outer edge**MOT #13**

2021-06-29 13:36

MOT test number

919347601727

Result**✓ Passed****Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12**

2021-06-28 15:30

MOT test number

624992355216

Result**✗ Failed****Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**MOT #11** 2020-08-27 15:03**MOT test number** 936449806812**Result** ✓ Passed**Minor** Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #10** 2019-12-13 17:25**MOT test number** 603841589459**Result** ✓ Passed**MOT #9** 2019-12-13 09:49**MOT test number** 401250562379**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #8** 2018-12-17 13:27**MOT test number** 742105911695**Result** ✓ Passed**MOT #7** 2018-12-12 15:40**MOT test number** 265706529721**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))**MOT #6** 2017-10-04 07:48**MOT test number** 569936293930**Result** ✓ Passed

**MOT #5** 2016-09-26 17:01**MOT test number** 117352169676**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-09-18 07:51**MOT test number** 862428887821**Result** ✓ Passed**MOT #3** 2014-09-29 11:06**MOT test number** 696132274222**Result** ✓ Passed**MOT #2** 2013-09-26 11:04**MOT test number** 446359063219**Result** ✓ Passed**MOT #1** 2012-08-29 14:43**MOT test number** 328982042202**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-21
Last registration	2023-07-04
Complete history	See info



Registration #1	2009-09-21	24 mi
Registration #2	2012-08-29	18.688 mi
Registration #3	2013-09-26	24.032 mi
Registration #4	2014-09-29	38.247 mi
Registration #5	2015-09-18	42.536 mi
Registration #6	2016-09-26	53.484 mi
Registration #7	2017-10-04	65.247 mi
Registration #8	2018-12-12	79.062 mi
Registration #9	2018-12-17	79.144 mi
Registration #10	2019-05-20	85.377 mi
Registration #11	2019-05-20	85.377 mi
Registration #12	2019-05-20	85.377 mi
Registration #13	2019-05-20	85.377 mi
Registration #14	2019-05-20	85.377 mi
Registration #15	2019-05-20	85.377 mi
Registration #16	2019-05-20	85.377 mi
Registration #17	2019-05-20	85.377 mi
Registration #18	2019-05-20	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3760 mm
Wheel base	2380 mm
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D13A-1267598