



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 3

Date 2023-04-29

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2023-04-28

Pictures 45

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date 2021-08-06

Pictures 0

Listing price [View report](#)

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-10
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	38
Total items failed	7

MOT #18	2023-05-09 12:29
MOT test number	935207843427
Result	✓ Passed
Next expiry date	2024-05-10
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2022-04-29 08:23
MOT test number	383088045234
Result	✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))



MOT #16

2021-05-06 13:36

MOT test number

127799613308

Result

✓ Passed

- Advice

Front Coil spring corroded nearside and offside (5.3.1 (b) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Play in steering rack inner joint(s)
- Advice

Engine covers and undertrays fitted
- Advice

Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor

Front Lower Suspension arm ball joint dust cover severely deteriorated nearside and offside (5.3.4 (b) (i))
- Advice

Exhaust corroded

**MOT #15**

2021-05-06 10:13

MOT test number

982094671600

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated nearside and offside (5.3.4 (b) (i))
- Advice** Engine covers and undertrays fitted
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Rear Brake pipe excessively corroded by tank (1.1.11 (c))
- Advice** Exhaust corroded
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Front Coil spring corroded nearside and offside (5.3.1 (b) (i))

MOT #14

2020-05-11 07:12

MOT test number

529985873394

Result**✓ Passed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material by tank (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Coil spring corroded nearside and offside (5.3.1 (b) (i))
- Advice** Engine covers and undertrays fitted

**MOT #13** 2019-05-13 15:43**MOT test number** 190999804599**Result** ✓ Passed

- Advice** Exhaust corroded
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material by tank both (1.1.11 (c))
- Advice** Engine covers and undertrays fitted

MOT #12 2019-05-13 11:43**MOT test number** 473821529232**Result** ✗ Failed

- Advice** Exhaust corroded
- Fail** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))
- Advice** Engine covers and undertrays fitted
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material by tank both (1.1.11 (c))

MOT #11 2018-05-09 08:12**MOT test number** 572745345831**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Inner tyres wearing on edges.

**MOT #10** 2017-05-09 08:13**MOT test number** 294267338158**Result** ✓ Passed**Advice** Nearside Front body damaged bumper area.**Advice** Nearside Front Inner tyre wearing on edge.**MOT #9** 2016-05-09 08:10**MOT test number** 486273235338**Result** ✓ Passed**Advice** Offside Front Outer tyre sidewall damaged.**MOT #8** 2015-05-12 12:13**MOT test number** 185802935166**Result** ✓ Passed**MOT #7** 2015-05-12 09:22**MOT test number** 857952735166**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #6** 2014-04-23 10:16**MOT test number** 769713914111**Result** ✓ Passed

**MOT #5** 2014-04-23 10:16**MOT test number** 126883014135**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2013-05-14 08:50**MOT test number** 738754133184**Result** ✓ Passed**MOT #3** 2013-04-24 17:24**MOT test number** 425294513102**Result** ✓ Passed**MOT #2** 2012-04-27 16:10**MOT test number** 748068812116**Result** ✓ Passed**MOT #1** 2011-11-26 09:24**MOT test number** 475580331486**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 May 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	10 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-12-04
Last registration	2023-05-09
Complete history	See info



Registration #1	2008-12-04	16 mi
Registration #2	2011-11-26	24.380 mi
Registration #3	2012-04-27	27.703 mi
Registration #4	2013-04-24	36.681 mi
Registration #5	2013-05-14	37.082 mi
Registration #6	2014-04-23	47.409 mi
Registration #7	2015-05-12	56.958 mi
Registration #8	2015-05-12	56.958 mi
Registration #9	2016-05-09	65.516 mi
Registration #10	2017-05-09	73.989 mi
Registration #11	2018-05-09	81.948 mi
Registration #12	2019-05-09	90.407 mi
Registration #13	2020-05-09	98.866 mi
Registration #14	2021-05-09	107.325 mi
Registration #15	2022-05-09	115.784 mi
Registration #16	2023-05-09	124.243 mi
Registration #17	2024-05-09	132.702 mi
Registration #18	2025-05-09	141.161 mi
Registration #19	2026-05-09	149.620 mi
Registration #20	2027-05-09	158.079 mi
Registration #21	2028-05-09	166.538 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564