



report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA GT
Colour	White
Year of manufacture	2013
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	137 BHP
Max. torque	235 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	56.5 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-12-22
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-20
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #9	2023-07-18 13:44
MOT test number	674527938928
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8	2022-07-20 08:23
MOT test number	114134811723
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7	2021-07-05 09:43
MOT test number	912551880498
Result	✓ Passed

**MOT #6** 2021-07-02 07:57**MOT test number** 247619675452**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #5** 2020-07-21 06:58**MOT test number** 134440255202**Result** ✓ Passed**MOT #4** 2019-06-03 11:10**MOT test number** 747509255178**Result** ✓ Passed**MOT #3** 2018-04-25 14:23**MOT test number** 292481178873**Result** ✓ Passed**MOT #2** 2017-04-01 08:58**MOT test number** 590110912224**Result** ✓ Passed**Advice** Items removed from driver's view prior to test sat nav.**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' small crack on windscreen. (8.3.1a)**MOT #1** 2016-04-07 16:55**MOT test number** 393528064035**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	D
Single payment (12 months)	£ 140,00,-
Single six month payment	£ 77,00,-
Total payable by 12 monthly instalments	£ 147,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	FH13FXA
Plate since	2019-03-29
Current registration	FH13FXA
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-07-30
Last registration	2023-07-18
Complete history	See info



Registration #1	2013-07-30	26 mi
Registration #2	2016-04-07	16.388 mi
Registration #3	2017-04-01	61.825 mi
Registration #4	2018-04-25	88.437 mi
Registration #5	2019-06-03	101.587 mi
Registration #6	2020-07-21	112.514 mi
Registration #7	2023-07-18	112.514 mi
Registration #8	2023-07-18	112.514 mi
Registration #9	2023-07-18	112.514 mi
Registration #10	2023-07-18	112.514 mi
Registration #11	2023-07-18	112.514 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4075 mm
Wheel base	2425 mm
Kerb weight	1210 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA3 3001481