





General information

Make	LAND ROVER
Model	DISCOVERY SDV6 COMMERCIAL SE
Colour	Grey
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	440 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	37.2 mpg
Consumption combined	35.3 mpg
CO2 emission	213 g/km
CO2 label	К







Internet history

Entry 2	
Date	2021-07-04
Pictures	10
Listing price	View report



source: yesauto.com

Entry	1

Date

Pictures

Listing price

2021-07-03 11

View report



source: cargurus.co.uk









MOT history

MOT expiry date	2025-04-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	20
Total items failed	1

МОТ #9	2024-04-09 15:07
MOT test number	555738887248
Result	Passed
Next expiry date	2025-04-08
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Standard fitment seat belt missing all rear seats missing	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8		2024-04-09 15:07
MOT test number		686146345339
Result		× Failed
Advice Nearside Rear Ty	re slightly damaged/cracking or perishing (5.2.3 (d	l) (ii))
Advice Offside Front Low rear bush (5.3.4 (a) (i))	ver Suspension arm pin or bush worn but not result	ing in excessive movement
Advice Offside Rear Tyr	e slightly damaged/cracking or perishing (5.2.3 (d)	(ii))
Advice Rear Standard fitment seat belt missing all rear seats missing		
Pass with rectification (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of	a single lamp or all lamps





MOT #7	2023-06-30 09:29
MOT test number	454410667517
Result	✓ Passed
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
Advice Offside Rear Brake pipe corroded, covered in grease or other material all real (1.1.11 (c))	ar brake pipes coated
Advice Offside Rear Passenger seat(s) missing at time of test	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive bushing (5.3.4 (a) (i))	e movement rear
Advice Rear Prop shaft bearing has slight play rubber bearing support deteriorated	(6.1.7 (b) (i))

MOT #6		2022-06-30 15:58
MOT test	number	904198972698
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement back bushing slight movement (5.3.4 (a) (i))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Passenger seat(s) missing at time of test	

MOT #5	2021-07-27 13:53
MOT test number	634839273470
Result	✓ Passed

MOT #4	2021-03-23 16:57
MOT test number	741446351151
Result	✓ Passed





MOT #3	2021-03-17 16:52
MOT test number	893445658071
Result	🗙 Failed
MAJOR Rear Registration plate does not conform to the specified requirements letters/numbers (0.1 (d))	Incorrect spacing of
MAJOR Front Registration plate does not conform to the specified requirements letters/numbers (0.1 (d))	s Incorrect spacing of
MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enoug Outer wall (5.2.3 (d) (i))	gh to reach the ply or cords
MOT #2	2020-03-27 09:39
MOT test number	195868168613
Result	✓ Passed
MOT #1	2019-04-01 16:49
MOT test number	806999635438

Result

🗸 Passed



Tax & MOT check

	✓ xed		√ МОТ
Tax due: 1 March 2025 Tax status		Expires: 8 April 2025	Valid until 1 March
Days left			305
MOT expiry date			8 April 2025
Full MOT history			See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	 4
Category	 AMPLI
Туре	W CON

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-05-26
Last registration	2024-04-09
Complete history	See info



Registration #1	2016-05-26	21 mi
Registration #2	2019-04-01	52.872 mi
Registration #3	2020-03-27	63.972 mi
Registration #4	2021-03-17	74.696 mi
Registration #5	2021-03-23	74.895 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.277 esi

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2009 mm
Height	1887 mm
Length	4848 mm
Kerb weight	2602 kg
Max. allowed weight	3230 kg
Additional information	
Additional information Fuel tank capacity	82 I
	82 I Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5