





General information

| Make | AUDI |
|---------------------|-----------------------------|
| Model | Q3 TDI S LINE BLACK EDITION |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 126 mph |
| 0 - 60 mph | 9.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 340 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 124 g/km |
| CO2 label | D |





Internet history

Entry 1

Date Pictures 2022-06-25

26

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-01-02 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 2 |

| MOT #5 | 2024-01-03 13:51 |
|------------------|------------------|
| MOT test number | 985886539351 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-02 |

| MOT #4 | | 2023-06-23 10:41 |
|--|--|------------------|
| MOT test | number | 828044288815 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front void | | |
| bushes (5.3.4 (a) (i)) | | |

| MOT #3 | 2022-06-24 11:01 |
|-----------------|------------------|
| MOT test number | 616666977002 |
| Result | ✓ Passed |

| MOT #2 | 2022-06-24 11:01 |
|-------------------------|--|
| MOT test number | 258892232292 |
| Result | × Failed |
| Pass with rectification | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Pass with rectification | Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |





| MOT #1 | 2 | 021-09-16 13:40 |
|---|---|-----------------|
| MOT test | number | 793129259605 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d |) (i)) |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice | Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |



Tax & MOT check

| √ Taxed | √ МОТ |
|----------------------------|----------------------------|
| Tax due: 1 January 2025 | Expires: 2 January 2025 |
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 2 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-09-28 |
| Last registration | 2024-01-03 |
| Complete history | <u>See info</u> |



| Registration #1 | 2018-09-28 | 29 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-09-16 | 88.078 mi |
| Registration #3 | 2022-06-24 | 107.484 mi |
| Registration #4 | 2022-06-24 | 107.484 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 85% |
| Pedestrian | 52% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1831 mm |
| Height | 1608 mm |
| Length | 4388 mm |
| Wheel base | 2603 mm |
| Kerb weight | 1485 kg |
| Max. allowed weight | 2085 kg |
| Additional information | |
| Fuel tank capacity | 64 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | DFTA117425 |