



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE S
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





MOT history

MOT expiry date	2025-02-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	18
Total items failed	11

MOT #18	2024-02-19 09:52
MOT test number	956221304981
Result	✓ Passed
Next expiry date	2025-02-18

MOT #17	2024-02-15 09:41
MOT test number	323651159854
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #16	2023-02-17 17:36
MOT test number	469612205924
Result	✓ Passed

MOT #15	2022-02-11 09:47
MOT test number	525725475745
Result	✓ Passed

MOT #14	2021-02-10 12:01
MOT test number	691298448454
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened all four discs (1.1.14 (a) (ii))

**MOT #13** 2021-01-19 17:11**MOT test number** 883367716182**Result** ✗ Failed**Advice** Nearside Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2019-06-26 10:40**MOT test number** 644452798289**Result** ✓ Passed**MOT #11** 2018-10-19 12:45**MOT test number** 387577477704**Result** ✓ Passed**MOT #10** 2018-10-18 15:17**MOT test number** 813875100403**Result** ✗ Failed**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**MOT #9** 2018-08-28 08:26**MOT test number** 387867566462**Result** ✓ Passed



MOT #8 2017-09-13 13:11

MOT test number 301596311685

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)
- Advice** Central Front registration plate deteriorated but not likely to be misread cracked (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2016-09-19 09:59

MOT test number 599752050381

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside & offside rear tyres cracked- NO visible cords
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-09-11 16:16

MOT test number 793305155666

Result ✓ Passed

- Advice** Rear Both rear tyres cracking

**MOT #5** 2015-09-11 10:06**MOT test number** 924208574931**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Both rear tyres cracking**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2014-09-15 11:18**MOT test number** 389458154412**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-09-17 14:41**MOT test number** 156190263201**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #2** 2013-09-17 14:41**MOT test number** 827770263211**Result** ✗ Failed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #1** 2012-10-02 14:20**MOT test number** 527536872285**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-09
Last registration	2024-02-19
Complete history	See info



Registration #1	2009-11-09	13 mi
Registration #2	2012-10-02	29.225 mi
Registration #3	2013-09-17	39.506 mi
Registration #4	2014-09-15	49.308 mi
Registration #5	2015-09-11	58.544 mi
Registration #6	2015-09-11	58.584 mi
Registration #7	2016-09-19	68.779 mi
Registration #8	2017-09-13	77.976 mi
Registration #9	2018-08-28	86.950 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

884000