





report date: 2024-03-29

General information

| Make | AUDI |
|---------------------|-------------------|
| Model | A5 TDI DPF S LINE |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 140 mph |
| 0 - 60 mph | 8.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 170 BHP |
|-------------------------|---------------------|
| Max. torque | 350 Nm at 2.500 rpm |
| Engine capacity | 1.968 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history


Entry 1

Date 2021-06-03

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

| MOT history | Μ | OT | h | is | to | rv |
|-------------|---|----|---|----|----|----|
|-------------|---|----|---|----|----|----|

| MOT expiry date | 2024-10-06 |
|--------------------|------------|
| MOT pass rate | 65 % |
| MOT passed | 11 |
| Failed MOT tests | 6 |
| Total advice items | 30 |
| Total items failed | 11 |

| MOT #17 | 2023-10-05 08:38 |
|------------------|------------------|
| MOT test number | 649705874060 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-06 |

| MOT #16 | 2022-09-21 12:39 |
|--|------------------|
| MOT test number | 382186081980 |
| Result | ✓ Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #15 | 2021-09-28 16:27 |
|---|------------------------------|
| MOT test number | 662939791583 |
| Result | ✓ Passed |
| | |
| MOT #14 | 2020-09-30 14:42 |
| MOT test number | 186649766845 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/ | worn on edge (5.2.3 (e)) |
| Advice Nearside Rear Child Seat fitted not allowing f | ull inspection of adult belt |

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #13 2019-10-07 15:15

MOT test number 211826227298

MOT #12 2018-09-26 15:28

MOT test number 453377484021

Result Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2018-09-25 10:09

MOT test number 766182615550

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10 2017-10-04 10:40

MOT test number 175076526768

Result ✓ Passed

Advice Offside wire hanging from underside

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside side under trims missing

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2017-09-27 11:46

MOT test number 276454601500

Result X Failed

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% side light (1.1.A.3b)

Fail Nearside Rear Rear position lamp(s) not working no plate light inop (1.1.A.3b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Advice Offside side under trims missing

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% stop lamp (1.1.A.3b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Central Exhaust system not adequately supported (7.1.1)

Advice Offside wire hanging from underside

CarCheck.co.uk page 5/14



Pass with rectification

KM59XFT

report date: 2024-03-29

MOT #8

MOT test number

176483891722

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #6
 2015-03-23 12:16

 MOT test number
 566372085002

 Result
 ✓ Passed

 MOT #5
 2015-03-23 12:16

 MOT test number
 518672285004

 Result
 X Failed

MOT #4

MOT test number

2013-11-28 12:06

278482533350

Result


Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Nearside Rear position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 6/14



report date: 2024-03-29



| MOT #2 | 2012-11-10 10:18 |
|--|------------------|
| MOT test number | 405385712308 |
| Result | ✓ Passed |
| Notice Front discs worn and lip on edges | |

| MOT #1 | 2012-11-06 10:22 |
|---|------------------|
| MOT test number | 117491412394 |
| Result | X Failed |
| Advice Offside Rear Shock absorber has a light misting of oil (2.7.3) | |
| Notice Front discs worn and lip on edges | |
| Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3) | |

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 6 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I | |
|--|-------------|
| | |
| THE STATE OF THE S | |
| *************************************** | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| *************************************** | |
| ************* | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| | |
| Number of plates | |
| Current registration | OK SIE |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2010-01-25 |
| Last registration | 2023-10-05 |
| Complete history | See info |



| Registration #1 | 2010-01-25 | 22 mi |
|------------------|------------|------------|
| Registration #2 | 2012-11-06 | 80.412 mi |
| Registration #3 | 2012-11-10 | 80.420 mi |
| Registration #4 | 2013-11-28 | 100.156 mi |
| Registration #5 | 2015-03-23 | 126.289 mi |
| Registration #6 | 2016-03-03 | 128.615 mi |
| Registration #7 | 2016-03-07 | 128.165 mi |
| Registration #8 | 2017-09-27 | 137.865 mi |
| Registration #9 | 2017-10-04 | 137.865 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 84% |
| Pedestrian | 39% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1854 mm |
|---------------------|---------|
| Height | 1372 mm |
| Length | 4625 mm |
| Wheel base | 2751 mm |
| Kerb weight | 1470 kg |
| Max. allowed weight | 1975 kg |

Additional information

| Fuel tank capacity | 65 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats CarCheck.co.uk | 4 page 14/ |

Number of axles 2

Engine number CAH 129958