



J883CEV

report date: 2024-03-28

General information

Make	NISSAN
Model	FIGARO
Colour	Purple
Year of manufacture	1991
Gearbox	-

Engine & fuel consumption

Engine capacity	987 cc
Fuel type	Petrol





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-19
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-08-29
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	17
Total items failed	13

MOT #19 2024-04-25 15:53

MOT test number 137313234959

Result ✗ Failed

**Minor** Nearside Front Lower Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail** Nearside Lower Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting excessive corrosion down full length of n/s sill within 30cm of rear suspension component and seat belt anchor (6.2.2 (d) (i))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Central Rear Brake pipe inadequately clipped or supported close to rear axel (1.1.11 (d) (i))

**Advice** Fuel and brake lines covered in sealant preventing full examination

**Minor** Offside Front Lower Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Rear Rear fog lamp missing (4.5.1 (a) (ii))

**MOT #18** 2021-08-27 13:07**MOT test number** 326753120159**Result** ✓ Passed**Advice** Engine covers and undertrays fitted obscuring some components**Advice** Underside heavily undersealed**MOT #17** 2020-07-31 08:59**MOT test number** 276714132083**Result** ✓ Passed**Advice** Underside heavily undersealed**MOT #16** 2019-08-23 13:21**MOT test number** 651513235289**Result** ✓ Passed**MOT #15** 2019-08-23 13:21**MOT test number** 953995317263**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2018-08-23 10:27**MOT test number** 791330862256**Result** ✓ Passed**MOT #13** 2017-08-22 15:45**MOT test number** 643119659271**Result** ✓ Passed

**MOT #12** 2016-08-09 13:04**MOT test number** 413860801588**Result** ✓ Passed**MOT #11** 2016-08-09 10:54**MOT test number** 999903413265**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Exhaust system not adequately supported (7.1.1)**MOT #10** 2015-08-04 10:01**MOT test number** 666136015268**Result** ✓ Passed**MOT #9** 2015-08-04 10:01**MOT test number** 708266415221**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2014-08-30 12:40**MOT test number** 118932644220**Result** ✓ Passed**Advice** Offside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #7** 2013-10-08 13:13**MOT test number** 339451083220**Result** ✓ Passed

**MOT #6** 2011-01-05 10:12**MOT test number** 967855301080**Result** ✗ Failed**Pass with rectification** Rear fog lamp emits a light other than red (1.3.2e)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2011-01-05 10:12**MOT test number** 329795201057**Result** ✓ Passed**MOT #4** 2009-12-12 11:35**MOT test number** 630126749385**Result** ✓ Passed**MOT #3** 2008-12-30 14:56**MOT test number** 520335868354**Result** ✓ Passed**MOT #2** 2007-11-26 12:48**MOT test number** 531130737365**Result** ✓ Passed**MOT #1** 2007-11-19 12:38**MOT test number** 114863327393**Result** ✗ Failed**Fail** Parking brake is not capable of being maintained in operation by direct mechanical action only (3.1.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	1991-05-01
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	1991-05-01	26 mi
Registration #2	2007-11-19	54.539 mi
Registration #3	2007-11-26	54.539 mi
Registration #4	2008-12-30	94.021 mi
Registration #5	2009-12-12	19.937 mi
Registration #6	2011-01-05	101.653 mi
Registration #7	2013-10-08	102.435 mi
Registration #8	2014-08-30	107.437 mi
Registration #9	2015-08-04	70.377 mi
Registration #10	2016-08-09	115.372 mi
Registration #11	2016-08-09	115.372 mi
Registration #12	2016-08-09	115.372 mi
Registration #13	2016-08-09	115.372 mi
Registration #14	2016-08-09	115.372 mi
Registration #15	2016-08-09	115.372 mi
Registration #16	2016-08-09	115.372 mi
Registration #17	2016-08-09	115.372 mi
Registration #18	2016-08-09	115.372 mi
Registration #19	2016-08-09	115.372 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Additional information

Engine number	14709
---------------	-------