



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	Red
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	0
Listing price	<a href="#">View report</a>

source: autoonline.co.uk



## MOT history

MOT expiry date	2025-02-07
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	13

MOT #11	2024-02-07 14:34
MOT test number	275055851860
Result	✓ Passed
Next expiry date	2025-02-07

MOT #10	2024-02-05 12:25
MOT test number	701283864443
Result	✗ Failed
Fail	Emissions unable to be completed (8.2.1.2 (d))
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Steering rack has excessive free play detected at the steering wheel (steering rack fitted) offside inner rack end (2.3 (a) (i))
Fail	Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

MOT #9	2023-02-01 13:22
MOT test number	748733998413
Result	✓ Passed
Advice	Nearside Play in steering rack inner joint(s)
Advice	Offside Play in steering rack inner joint(s)

**MOT #8** 2023-01-30 10:53**MOT test number** 747929584265**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Offside Play in steering rack inner joint(s)**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Nearside Play in steering rack inner joint(s)**MOT #7** 2022-02-08 10:18**MOT test number** 944930307524**Result** ✓ Passed**MOT #6** 2021-11-11 15:09**MOT test number** 353643981341**Result** ✓ Passed**MOT #5** 2021-11-03 11:32**MOT test number** 217567145060**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen wiper does not clear the windscreen effectively both sides (3.4 (b) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #4**

2019-09-26 09:24

**MOT test number**

728288807705

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3**

2018-09-27 09:43

**MOT test number**

729115962679

**Result**

✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #2**

2017-09-25 13:56

**MOT test number**

676508971153

**Result**

✓ Passed

**Advice** Coolant leak water pump**Advice** Front wipers judder across screen**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #12016-09-28 10:38

MOT test number619330249058

Result

✓ Passed

- Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
7 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	7 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	NL63KSX
Plate since	2019-09-29
Current registration	NL63KSX
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-09-30
Last registration	2024-02-07
Complete history	<a href="#">See info</a>



Registration #1	2013-09-30	22 mi
Registration #2	2016-09-28	21.457 mi
Registration #3	2017-09-25	27.558 mi
Registration #4	2018-09-27	34.776 mi
Registration #5	2019-09-26	44.458 mi
Registration #6	2020-09-25	50.377 mi
Registration #7	2021-11-03	50.449 mi
Registration #8	2022-09-25	50.377 mi
Registration #9	2023-09-25	50.377 mi
Registration #10	2024-02-07	50.377 mi
Registration #11	2024-02-07	50.377 mi
Registration #12	2024-02-07	50.377 mi
Registration #13	2024-02-07	50.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

**Engine number**

0341597