



General information

Make	FIAT
Model	500 C SPORT
Colour	Red
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-03-30
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-08
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	26
Total items failed	19

MOT #16 2024-04-17 13:17

MOT test number 692994153486

Result ✓ Passed

Next expiry date 2025-05-08

Advice Nearside Rear exhaust box corroded

Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords worn inner edge (5.2.3 (d) (i))

MOT #15 2024-04-17 08:31

MOT test number 335225745932

Result ✗ Failed

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords worn inner edge (5.2.3 (d) (i))

Minor Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear exhaust box corroded

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #14** 2023-04-27 07:56**MOT test number** 118229394265**Result** ✓ Passed**Advice** Offside Front tyre worn inner edge**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2022-05-09 12:03**MOT test number** 784674423089**Result** ✓ Passed**MOT #12** 2021-07-12 08:59**MOT test number** 989259396264**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge low (5.2.3 (e))**MOT #11** 2020-07-18 10:28**MOT test number** 354966457946**Result** ✓ Passed**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush perished (5.3.2 (c))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge low (5.2.3 (e))

**MOT #10** 2020-07-18 08:53**MOT test number** 774237080921**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge low (5.2.3 (e))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush perished (5.3.2 (c))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #9** 2019-07-16 12:43**MOT test number** 620982381900**Result** ✓ Passed**MOT #8** 2019-07-12 09:03**MOT test number** 625621248314**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #7** 2018-07-19 15:11**MOT test number** 488559479276**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-07-19 09:11**MOT test number** 118202535227**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2017-07-20 11:54**MOT test number** 113480694057**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2016-07-22 09:41**MOT test number** 992833340641**Result** ✓ Passed



MOT #3	2015-09-01 16:09
MOT test number	461947323498
Result	✓ Passed

MOT #2	2015-09-01 00:00
MOT test number	169716988988
Result	✗ Failed
<div><div>Fail</div> Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)</div> <div><div>Fail</div> Offside Windscreen washer provides insufficient washer liquid (8.2.3)</div> <div><div>Fail</div> Offside Rear rear brake binding (3.7.B.1)</div> <div><div>Fail</div> Nearside Windscreen washer provides insufficient washer liquid (8.2.3)</div>	

MOT #1	2014-07-12 11:17
MOT test number	927053894137
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 May 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	8 May 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-30
Last registration	2024-04-17
Complete history	See info



Registration #1	2010-06-30	12 mi
Registration #2	2014-07-12	23.227 mi
Registration #3	2015-09-01	35.530 mi
Registration #4	2015-09-01	35.530 mi
Registration #5	2016-07-22	41.133 mi
Registration #6	2017-07-20	50.845 mi
Registration #7	2018-07-19	62.300 mi
Registration #8	2018-07-19	62.300 mi
Registration #9	2019-07-12	72.402 mi
Registration #10	2019-07-12	72.402 mi
Registration #11	2019-07-12	72.402 mi
Registration #12	2019-07-12	72.402 mi
Registration #13	2019-07-12	72.402 mi
Registration #14	2019-07-12	72.402 mi
Registration #15	2019-07-12	72.402 mi
Registration #16	2019-07-12	72.402 mi
Registration #17	2019-07-12	72.402 mi
Registration #18	2019-07-12	72.402 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6058766