



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | S40 D3 ES |
| Colour | White |
| Year of manufacture | - |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 1.500 rpm |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 55.4 mpg |



LABEL UNKNOWN

**MOT history**

| | |
|-------------------------|--|
| MOT #8 | 2019-04-01 16:10 |
| MOT test number | 860090188978 |
| Result | ✓ Passed |
| Next expiry date | 2020-09-30 |
| Minor | Offside Front Windscreen wiper blade defective (3.4 (b) (i)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm rear bush (5.3.4 (a) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) |
| Advice | Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2055017 (5.2.3 (e)) |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm rear bush (5.3.4 (a) (i)) |

| | |
|------------------------|--|
| MOT #7 | 2019-03-30 15:49 |
| MOT test number | 692319445414 |
| Result | ✗ Failed |
| Fail | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) |
| Fail | Nearside Front Position lamp not working (4.2.1 (a)) |
| Advice | Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 2055017 (5.2.3 (e)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Minor | Offside Front Windscreen wiper blade defective (3.4 (b) (i)) |

**MOT #6** 2018-03-24 17:02**MOT test number** 730956575641**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
- Advice** Offside Front Inner Tyre worn close to the legal limit on limit (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened & offside (3.5.1i)

MOT #5 2017-03-03 09:20**MOT test number** 782799420642**Result** ✓ Passed

- Advice** Engine cover fitted
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened inside edge (3.5.1i)
- Advice** Undertrays fitted
- Advice** Exhaust corroded

MOT #4 2016-03-08 15:58**MOT test number** 253933030356**Result** ✓ Passed

- Advice** Engine cover fitted
- Advice** Undertray fitted

MOT #3 2015-03-13 14:44**MOT test number** 887452975001**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #2** 2015-03-12 11:01**MOT test number** 946791275095**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2014-03-25 13:47**MOT test number** 996804484031**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------|
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |
| Owner | Period |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2011-03-31 |
| Last registration | 2019-04-01 |
| Complete history | See info |



| | | |
|-----------------|------------|------------|
| Registration #1 | 2011-03-31 | 22 mi |
| Registration #2 | 2014-03-25 | 57.227 mi |
| Registration #3 | 2015-03-12 | 77.444 mi |
| Registration #4 | 2015-03-13 | 77.476 mi |
| Registration #5 | 2016-03-08 | 92.764 mi |
| Registration #6 | 2019-04-01 | 100.000 mi |
| Registration #7 | 2019-04-01 | 100.000 mi |
| Registration #8 | 2019-04-01 | 100.000 mi |
| Registration #9 | 2019-04-01 | 100.000 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1504 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1012435 |