





report date: 2024-03-28

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Blue
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	194 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-16

Pictures 11

Listing price <u>View report</u>

PLEASE CALL
OUR TRADE
CENTRE ON
07950 744827



PLEASE CALL
OUR TRADE
CENTRE ON
07950 744827

PLEASE CALL
OUR TRADE
CENTRE ON
07950 744827

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2022-10-15
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	16
Total items failed	3

MOT #12		2021-10-06 08:19
MOT test	number	688134147981
Result		✓ Passed
Next exp	iry date	2022-10-15
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))		

MOT #11	2021-10-06 07:46
MOT test number	319579618571
Result	≍ Failed
Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3	3 (e))
Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteri	iorated (5.3.4 (b) (i))
Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2	2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9

MOT test number

645410536583

Result

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #8

MOT test number

Result

2018-09-25 14:53

181611963598

✓ Passed

MOT #7

MOT test number

936608512484

Result

√ Passed

MOT #6

MOT test number

266393785195

Result

Advice Offside Front steering system has slight play

 MOT #5
 2015-09-28 15:31

 MOT test number
 842923890863

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

 MOT #4
 2014-10-16 16:16

 MOT test number
 376579084496

 Result
 ✓ Passed

MOT #3 2014-03-22 13:22

MOT test number 135621584087

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2013-03-30 10:18

MOT test number 599119783035

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2012-03-28 15:17

MOT test number 517528982058

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax expired: 8 November 2021 X MOT

Expired: 15 October 2022

Tax status	Expired at 8 November 2021
Days left	902 days too late
MOT expiry date	15 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e when mistery	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full research	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-03-30
Last registration	2021-10-06
Complete history	See info



Registration #1	2009-03-30	18 mi
Registration #2	2012-03-28	29.170 mi
Registration #3	2013-03-30	44.753 mi
Registration #4	2014-03-22	59.922 mi
Registration #5	2014-10-16	69.611 mi
Registration #6	2015-09-28	80.863 mi
Registration #7	2016-09-20	92.115 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 44

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



MA09KZS report date: 2024-03-28

- C - C - C - C - C - C - C - C - C - C		_	
I)IMA	ncinne	- 入 7	weight
		· ·	WCIGIT

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ694008020

CarCheck.co.uk page 12/12