



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	Black
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-24
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	28
Total items failed	0

MOT #102024-03-21 14:34

MOT test number672952547773

Result✓ Passed

Next expiry date2025-03-24

- Advice**COVERS & UNDER TRAYS OBSCURING SOME ITEMS
- Advice**Nearside Rear Tyre slightly damaged/cracking or perishing TREADS SLIGHTLY PERISHED 2018 (5.2.3 (d) (ii))
- Advice**KNOCK FROM ELECTRIC POWER ASSIST STEERING COLUMN UNIT DURING FREE PLAY & LOCK TO LOCK CHECKS (ALL UJ'S OK) - ADVISE INVESTIGATION
- Advice**Offside Front Tyre worn close to legal limit/worn on edge INNER TREADS WORN (5.2.3 (e))
- Advice**Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice**AFLS LAMP ILLUMINATED
- Advice**Nearside Front Tyre worn close to legal limit/worn on edge INNER TREADS WORN (5.2.3 (e))
- Advice**NO COOLANT IN HEADER TANK

**MOT #9**

2023-03-21 13:24

MOT test number

832068929403

Result

✓ Passed

- Advice** AFLS LAMP ILLUMINATED
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** COVERS & UNDER TRAYS OBSCURING SOME ITEMS
- Advice** KNOCK FROM ELECTRIC POWER ASSIST STEERING COLUMN UNIT DURING FREE PLAY & LOCK TO LOCK CHECKS (ALL UJ'S OK) - ADVISE INVESTIGATION

MOT #8

2022-03-25 14:27

MOT test number

816004431629

Result

✓ Passed

- Advice** Engine covers and undertrays fitted covering some components
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rearmost bush perished (5.3.4 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Knock from lower steering column universal joint
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rearmost bush perished (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Damage to outer sidewall and perishing within tread (5.2.3 (d) (ii))
- Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #7

2021-03-15 16:30

MOT test number

905764867512

Result

✓ Passed

- Advice** Noise from steering universal joint

**MOT #6** 2019-06-19 11:16**MOT test number** 271015662453**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2018-06-20 16:38**MOT test number** 341573992517**Result** ✓ Passed**MOT #4** 2018-06-20 13:56**MOT test number** 819562125429**Result** ✗ Failed**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside washer jet low power and aim but still provides sufficient fluid**MOT #3** 2017-06-23 11:09**MOT test number** 335320793652**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both / cracking badly (4.1.E.1)**Advice** Offside Rear wall damaged**Advice** Nearside Rear cracking**MOT #2** 2016-06-24 13:32**MOT test number** 965724721092**Result** ✓ Passed



MOT #1	2015-06-20 12:50
MOT test number	658421075187
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK12FZR
Plate since	2019-03-29
Current registration	EK12FZR
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-03-12
Last registration	2024-03-21
Complete history	See info



Registration #1	2012-03-12	9 mi
Registration #2	2015-06-20	22.674 mi
Registration #3	2016-06-24	29.812 mi
Registration #4	2017-06-23	35.558 mi
Registration #5	2018-06-20	41.165 mi
Registration #6	2018-06-20	41.167 mi
Registration #7	2019-06-20	46.777 mi
Registration #8	2019-06-20	46.777 mi
Registration #9	2019-06-20	46.777 mi
Registration #10	2019-06-20	46.777 mi
Registration #11	2019-06-20	46.777 mi
Registration #12	2019-06-20	46.777 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDBU033549