



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	Silver
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2023-06-23
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	28
Total items failed	17

MOT #16	2022-06-24 06:01
MOT test number	335135272489
Result	✓ Passed
Next expiry date	2023-06-23

MOT #15	2022-06-07 11:28
MOT test number	574741965248
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Windscreen washer not working (3.5 (a))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Windscreen wiper not working (3.4 (a))

MOT #14	2019-04-10 10:36
MOT test number	857251496113
Result	✓ Passed
Advice	Offside Front mirror cracked

**MOT #13** 2018-05-03 15:06**MOT test number** 110907965136**Result** ✓ Passed**Advice** Offside Rear side marker light inop.**MOT #12** 2018-05-03 15:06**MOT test number** 457147115335**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear side marker light inop.**MOT #11** 2017-04-20 14:17**MOT test number** 557071686908**Result** ✓ Passed**MOT #10** 2016-10-25 09:46**MOT test number** 106433295579**Result** ✗ Failed**Fail** Windscreen wiper not operating automatically when switched on (8.2.1b)**Fail** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)



MOT #9 2015-07-23 11:29

MOT test number 817804405203

Result ✓ Passed

- Notice** Offside centre marker light not working
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Brake pedal rubber is worn
- Notice** RECOMMEND THAT BOTH FRONT TYRES ARE RENEWED
- Notice** Clutch pedal rubber is missing
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front brake pad wear warning light wire is broken

MOT #8 2015-07-23 11:29

MOT test number 568504605230

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside centre marker light not working
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Notice** Brake pedal rubber is worn
- Pass with rectification** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Notice** RECOMMEND THAT BOTH FRONT TYRES ARE RENEWED
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Clutch pedal rubber is missing
- Pass with rectification** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Notice** Nearside front brake pad wear warning light wire is broken

**MOT #7** 2014-06-18 10:20**MOT test number** 999809664163**Result** ✓ Passed**MOT #6** 2013-07-18 16:57**MOT test number** 206079993469**Result** ✓ Passed**Notice** Nail in offside front tyre**Notice** O/s rear top none obligatory lamp inoperative**MOT #5** 2012-07-19 13:37**MOT test number** 717321502237**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-07-25 11:12**MOT test number** 697556701277**Result** ✓ Passed**Notice** Nearside front seat missing**Notice** Roof led light unit faulty, offside rear.**Notice** Rear seats missing.

**MOT #3** 2011-07-13 16:53**MOT test number** 917704191153**Result** ✗ Failed**Notice** Rear seats missing.**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Side repeater not working (1.4.A.2c)**Notice** Nearside front seat missing**Notice** Roof led light unit faulty, offside rear.**Fail** Nearside Rear Rear position lamp(s) insecure (1.1.A.3a)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Exhaust mounting rubbers perishing.**MOT #2** 2010-07-05 15:10**MOT test number** 601646980152**Result** ✓ Passed**MOT #1** 2009-07-15 09:22**MOT test number** 812196599125**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2022

✕
MOT

Expired:
23 June 2023

Tax status

Expired at 31 December 2022

Days left

484 days too late

MOT expiry date

23 June 2023

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	OU08YLE
Plate since	2019-03-28
Current registration	OU08YLE
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-07-29
Last registration	2022-06-24
Complete history	See info



Registration #1	2008-07-29	12 mi
Registration #2	2009-07-15	17.839 mi
Registration #3	2010-07-05	31.296 mi
Registration #4	2011-07-13	54.087 mi
Registration #5	2011-07-25	54.087 mi
Registration #6	2012-07-19	72.927 mi
Registration #7	2013-07-18	94.878 mi
Registration #8	2014-06-18	99.700 mi
Registration #9	2015-06-20	99.700 mi
Registration #10	2016-06-20	99.700 mi
Registration #11	2017-06-20	99.700 mi
Registration #12	2018-06-20	99.700 mi
Registration #13	2019-06-20	99.700 mi
Registration #14	2020-06-20	99.700 mi
Registration #15	2021-06-20	99.700 mi
Registration #16	2022-06-24	99.700 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	1932 mm
Length	5413 mm
Kerb weight	1975 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20232357