



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Yellow
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	18
Total items failed	21

MOT #14	2024-02-23 12:54
MOT test number	194776787888
Result	✓ Passed
Next expiry date	2025-02-22
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2024-02-15 17:15
MOT test number	492589429510
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Nearside Headlamp insecure (4.1.1 (c))
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12	2023-02-10 10:04
MOT test number	258701509924
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11**

2022-01-25 16:03

MOT test number

394808671460

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10**

2022-01-24 12:35

MOT test number

182563950454

Result

✗ Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9**

2021-01-25 18:36

MOT test number

266922939444

Result

✓ Passed



MOT #8	2020-08-15 11:01
MOT test number	932212662973
Result	✗ Failed
Advice	Both front to rear brake pipes covered with plastic shield
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Minor	Window damaged but not adversely affecting driver's view stone chip in drivers view (3.2 (a) (i))
Advice	Sump slightly leaking oil
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Rear Brake pipe excessively corroded in clips (1.1.11 (c))
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure cracks deep enough to cords (5.2.3 (d) (ii))

MOT #7	2019-10-22 12:15
MOT test number	585717594278
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6	2019-10-21 11:14
MOT test number	564625788953
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Rear Service brake grabbing severely (1.2.1 (c))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #5	2017-11-06 16:06
MOT test number	973051461758
Result	✓ Passed
Advice	Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-11-04 12:35**MOT test number** 116728828595**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2016-11-03 17:23**MOT test number** 275099877062**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2015-11-16 12:22**MOT test number** 634227181723**Result** ✓ Passed**Advice** Front brake discs corroded**MOT #1** 2015-11-16 10:50**MOT test number** 463565403879**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake discs corroded**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-17
Last registration	2024-02-23
Complete history	See info



Registration #1	2013-01-17	6 mi
Registration #2	2015-11-16	25.062 mi
Registration #3	2015-11-16	25.062 mi
Registration #4	2016-11-03	35.717 mi
Registration #5	2016-11-04	35.717 mi
Registration #6	2017-11-06	44.941 mi
Registration #7	2019-10-21	65.425 mi
Registration #8	2019-10-22	65.427 mi
Registration #9	2019-10-23	65.427 mi
Registration #10	2019-10-24	65.427 mi
Registration #11	2019-10-25	65.427 mi
Registration #12	2019-10-26	65.427 mi
Registration #13	2019-10-27	65.427 mi
Registration #14	2019-10-28	65.427 mi
Registration #15	2019-10-29	65.427 mi
Registration #16	2019-10-30	65.427 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5

Number of axles	2
Engine number	U054847