



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI SPORT
Colour	Blue
Year of manufacture	2005
Top speed	125 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.999 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.9 mpg
CO2 emission	294 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-07-23
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-22
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	51
Total items failed	16

MOT #21	2021-08-09 14:17
MOT test number	286200366515
Result	✓ Passed
Next expiry date	2022-08-08
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Underside corroded (front and rear)

MOT #20	2021-08-02 17:24
MOT test number	617167335676
Result	✗ Failed
Fail	Central Prop shaft bearing likely to break up (6.1.7 (b) (ii))
Advice	Underside corroded (front and rear)
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #19**

2020-11-13 14:57

**MOT test number**

422022099428

**Result**

✓ Passed

- Advice** Nearside Rear brake slightly binding
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear brake slightly binding
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2019-11-25 15:32

**MOT test number**

317100767255

**Result**

✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame pin or bush worn but not resulting in excessive movement ALL (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Exhaust heatshield loose
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))



MOT #17

2019-11-25 15:15

MOT test number

687906410719

Result		✗ Failed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Sub-frame pin or bush worn but not resulting in excessive movement ALL (5.3.4 (a) (i))	
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Fail	Bonnet cannot be secured in the closed position (3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))	
Advice	Rear Exhaust heatshield loose	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	

**MOT #16**

2019-11-21 14:37

**MOT test number**

993832864989

**Result**

✗ Failed

**Fail** Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Fail** Emissions not tested disconnected at front flexi (8.2.2.2 (e))**Advice** Heavy corrosion to rear suspension, sill covers fitted unable to check sills.**Advice** Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15**

2018-07-04 09:33

**MOT test number**

361280618856

**Result**

✓ Passed

**MOT #14**

2018-06-28 10:48

**MOT test number**

364740006347

**Result**

✗ Failed

**Fail** Undertray likely to become detached (6.2.1 (a) (ii))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Steering column universal joint modified, but not inappropriately (2.1.3 (f) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**MOT #13** 2017-06-21 08:49**MOT test number** 399754519909**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2016-07-09 09:32**MOT test number** 344055136045**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-07-06 12:07**MOT test number** 757167885121**Result** ✓ Passed**MOT #10** 2014-06-23 13:46**MOT test number** 708804774111**Result** ✓ Passed**MOT #9** 2013-06-06 17:27**MOT test number** 209927853126**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2013-06-06 12:39**MOT test number** 555237853193**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-06-19 14:44**MOT test number** 189241272172**Result** ✓ Passed**MOT #6** 2012-06-18 12:32**MOT test number** 786400472147**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Bonnet cannot be secured in the closed position (8.4.1)**MOT #5** 2011-08-12 11:34**MOT test number** 866824321208**Result** ✓ Passed**MOT #4** 2010-08-12 10:19**MOT test number** 181534120236**Result** ✓ Passed**Notice** Battery flat when went to start vehicle 15 mins after customer left vehicle had to jump start**Notice** Judder from rear brakes on road





MOT #3 2009-08-06 11:56

MOT test number 550278819205

Result ✓ Passed

**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #2 2008-08-04 11:46

MOT test number 264507518240

Result ✓ Passed

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1 2008-07-29 13:13

MOT test number 534361218281

Result ✗ Failed

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
10 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	10 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-04-20
Last registration	2021-08-09
Complete history	<a href="#">See info</a>



Registration #1	2005-04-20	24 mi
Registration #2	2008-07-29	41.054 mi
Registration #3	2008-08-04	41.258 mi
Registration #4	2009-08-06	52.475 mi
Registration #5	2010-08-12	60.879 mi
Registration #6	2011-08-12	70.590 mi
Registration #7	2012-06-18	82.741 mi
Registration #8	2012-06-19	82.745 mi
Registration #9	2013-06-06	93.700 mi
Registration #10	2013-06-06	93.700 mi
Registration #11	2014-06-23	103.518 mi
Registration #12	2015-07-06	112.730 mi
Registration #13	2015-06-20	112.730 mi
Registration #14	2015-06-20	112.730 mi
Registration #15	2015-06-20	112.730 mi
Registration #16	2015-06-20	112.730 mi
Registration #17	2015-06-20	112.730 mi
Registration #18	2015-06-20	112.730 mi
Registration #19	2015-06-20	112.730 mi
Registration #20	2015-06-20	112.730 mi
Registration #21	2015-06-20	112.730 mi
Registration #22	2015-06-20	112.730 mi
Registration #23	2015-06-20	112.730 mi
Registration #24	2015-06-20	112.730 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5



Number of seats	5
Number of axles	2
Engine number	BKS 005827