



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-01-21
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-27
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	19
Total items failed	14

MOT #16	2024-03-28 14:11
MOT test number	632582146595
Result	✓ Passed
Next expiry date	2025-03-27
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2024-03-28 09:07
MOT test number	355632001546
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #14	2023-02-23 16:16
MOT test number	523926912140
Result	✓ Passed

**MOT #13** 2023-02-23 14:58**MOT test number** 574373935501**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #12** 2022-02-02 11:59**MOT test number** 764349593549**Result** ✓ Passed**MOT #11** 2021-02-10 09:50**MOT test number** 859890184701**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2020-02-27 10:56**MOT test number** 433696284975**Result** ✓ Passed**MOT #9** 2020-02-26 16:05**MOT test number** 374666439772**Result** ✗ Failed**Fail** Nearside Front Inner Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))

**MOT #8** 2019-03-21 16:51**MOT test number** 474905575307**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2019-03-21 16:30**MOT test number** 809454419572**Result** ✗ Failed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Front Headlamp aim so that beam "kick up" is not visible on the screen Nearside / Offside (4.1.2 (a))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #6** 2018-03-28 13:10**MOT test number** 407328243388**Result** ✓ Passed**MOT #5** 2018-03-28 09:29**MOT test number** 863399122553**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #4** 2017-04-11 10:55**MOT test number** 197474584852**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #3 2017-04-11 09:58**MOT test number** 395435433656**Result** ✗ Failed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #2 2016-03-02 15:56**MOT test number** 907475452731**Result** ✓ Passed**MOT #1** 2015-02-13 12:50**MOT test number** 738224945039**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 May
Days left	368
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-05
Last registration	2024-03-28
Complete history	See info



Registration #1	2012-03-05	11 mi
Registration #2	2015-02-13	17.820 mi
Registration #3	2016-03-02	29.218 mi
Registration #4	2017-04-11	47.665 mi
Registration #5	2017-04-11	47.665 mi
Registration #6	2018-03-28	61.178 mi
Registration #7	2018-03-28	61.179 mi
Registration #8	2019-03-21	74.494 mi
Registration #9	2019-03-21	74.494 mi
Registration #10	2019-03-21	74.494 mi
Registration #11	2019-03-21	74.494 mi
Registration #12	2019-03-21	74.494 mi
Registration #13	2019-03-21	74.494 mi
Registration #14	2019-03-21	74.494 mi
Registration #15	2019-03-21	74.494 mi
Registration #16	2019-03-21	74.494 mi
Registration #17	2019-03-21	74.494 mi
Registration #18	2019-03-21	74.494 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2041867