



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TDI
Colour	Black
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	112 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-05-21
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2023-10-06
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	54
Total items failed	22

MOT #18	2022-09-29 12:10
MOT test number	259029022827
Result	✓ Passed
Next expiry date	2023-10-06

MOT #17	2022-09-28 08:50
MOT test number	870378919381
Result	✗ Failed
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #16	2021-10-06 10:48
MOT test number	697047673762
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #15** 2020-10-07 15:32**MOT test number** 668492233500**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2020-10-07 09:44**MOT test number** 362142591339**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Central Rear Seat belt retracting mechanism defective (7.1.2 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #13** 2019-07-29 09:59**MOT test number** 948467228707**Result** ✓ Passed

**MOT #12**

2018-07-31 12:21

MOT test number

989322458291

Result

✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Parking brake lever has little reserve travel
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear exhaust box deteriorated
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front seatbelt stalk casing damaged but still functioning
- Advice** Winter tyre fitted to offside front wheel

MOT #11

2018-07-28 08:58

MOT test number

602819993559

Result

✗ Failed

- Fail** Central Exhaust system insecure (6.1.2 (a))
- Advice** Parking brake lever has little reserve travel
- Advice** Rear exhaust box deteriorated
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front seatbelt stalk casing damaged but still functioning
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Winter tyre fitted to offside front wheel
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10**

2018-07-20 13:36

MOT test number

483266946736

Result**✗ Failed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear exhaust backbox corroded

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MOT #9

2017-07-29 14:48

MOT test number

666406708030

Result**✓ Passed**

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear tyre deteriorated

Advice Nearside Front Nail in tyre

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both side inner back (2.4.G.2)

Advice Offside Front Inner Tyre worn close to the legal limit and outer (4.1.E.1)

Advice Nearside Front Valve stem slightly damaged deteriorated. (4.1.D.1e)

Advice Items removed from driver's view prior to test

Advice Rear exhaust box deteriorated.

**MOT #8** 2017-07-04 10:27**MOT test number** 253431995148**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement back (2.4.G.2)**Advice** Nearside Rear Nail in tyre**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Headlamp aim not tested (1.8.A.1c)**Advice** Rear exhaust box deteriorated**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement back (2.4.G.2)**Advice** Nearside Front Nail in tyre**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-05-17 11:06**MOT test number** 483706911603**Result** ✓ Passed**MOT #6** 2015-12-08 17:13**MOT test number** 343090708169**Result** ✓ Passed**Advice** Rear exhaust corroded**Advice** Under trays fitted**Advice** Slight noise on nearside front wheel bearing

**MOT #5** 2015-12-08 09:29**MOT test number** 787729765042**Result** ✗ Failed**Advice** Slight noise on nearside front wheel bearing**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Under trays fitted**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front wheels require tracking**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear exhaust corroded**MOT #4** 2014-12-09 12:39**MOT test number** 837673444329**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #3** 2013-12-09 15:49**MOT test number** 109983843379**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-06-04 17:07**MOT test number** 598895653192**Result** ✓ Passed



MOT #1	2013-06-04 17:07
MOT test number	469005453174
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✗
MOT

Expired:
6 October 2023

Tax status	Valid until 1 July
Days left	64
MOT expiry date	6 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LL10YZD
Plate since	2020-03-28
Current registration	 LL10YZD
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-08
Last registration	2022-09-29
Complete history	See info



Registration #1	2010-06-08	21 mi
Registration #2	2013-06-04	41.373 mi
Registration #3	2013-12-09	48.122 mi
Registration #4	2014-12-09	54.358 mi
Registration #5	2015-12-08	60.142 mi
Registration #6	2015-12-08	60.146 mi
Registration #7	2016-05-17	62.224 mi
Registration #8	2017-07-04	71.063 mi
Registration #9	2017-07-29	71.990 mi
Registration #10	2018-07-20	83.990 mi
Registration #11	2019-06-20	95.997 mi
Registration #12	2019-06-20	95.997 mi
Registration #13	2019-06-20	95.997 mi
Registration #14	2019-06-20	95.997 mi
Registration #15	2019-06-20	95.997 mi
Registration #16	2019-06-20	95.997 mi
Registration #17	2019-06-20	95.997 mi
Registration #18	2019-06-20	95.997 mi
Registration #19	2019-06-20	95.997 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1157 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 727845