






report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI TDV SE
Colour	Blue
Year of manufacture	2008
Top speed	143 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	180 BHP
Max. torque	379 Nm at 1.400 rpm
Engine capacity	2.698 cc
Cylinders	6
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-09-04
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #16	2023-09-05 12:25
MOT test number	355566302230
Result	✓ Passed
Next expiry date	2024-09-04

MOT #15		2022-09-02 11:46
MOT test	number	184002084818
Result		✓ Passed
Advice	Nearside Front Suspension rod ball joint has slight play front lower (5.3.4 (a) (i))	
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension rod ball joint has slight play rear lower (5.3.4 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/12



MOT #14 2022-08-27 13:43

MOT test number 619200088295

Result X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))

Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))

Advice Offside Rear Lens light damaged

Fail Offside Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))

MOT #13 2021-07-30 08:54

MOT test number 548968631275

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2020-08-08 10:34

MOT test number 873720668146

MOT #11 2019-03-08 15:09

MOT test number 659117240618

Result
✓ Passed

CarCheck.co.uk page 3/12



OE57XAZ

report date: 2024-03-28

MOT #10	2018-03-10 09:31
MOT test number	894256880844
Result	✓ Passed
MOT #9	2017-03-04 11:58
MOT test number	264214054055
Result	✓ Passed
MOT #8	2016-03-05 08:59
MOT test number	300761340831
Result	✓ Passed
MOT #7	2015-03-10 08:41
MOT test number	159839465048
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Tronc Brake pad(s) wearing timi (5.5.1g)	
MOT #6	2014-03-01 11:07
MOT test number	607190364064
Result	✓ Passed
MOT #5	2013-03-11 11:53
MOT test number	898720873093
Result	✓ Passed
MOT #4	2013-03-11 11:53
MOT test number	325830373099
Result	× Failed
Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)	
rass with rettilication inearsing Real Stop lattice for Working (1.2.10)	

CarCheck.co.uk page 4/12



MOT #3	2012-07-13 10:40
MOT test number	259245892415
Result	✓ Passed
MOT #2	2011-07-13 09:19
MOT test number	505654091106
Result	✓ Passed
MOT #1	2011-02-08 09:58
MOT test number	999899231063
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



✓ MOT

Tax expired: 2 January 2024

Expires: 4 September 2024

Tax status	Expired at 2 January 2024
Days left	118 days too late
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
	1
Band	ı
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

OE57XAZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

funder scincole

See in this check if this AUDI had different number plates.

More info >

CarCheck.co.uk page 9/12



OE57XAZ

report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12




OE57XAZ

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-02-08
Last registration	2023-09-05
Complete history	See info



Registration #1	2008-02-08	12 mi
Registration #2	2011-02-08	8.270 mi
Registration #3	2011-07-13	10.111 mi
Registration #4	2012-07-13	21.681 mi
Registration #5	2013-03-11	29.483 mi
Registration #6	2014-03-01	35.061 mi
Registration #7	2015-03-10	42.398 mi
Registration #8	2016-03-05	50.829 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1570 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number CAM 015612