





report date: 2024-03-29

General information

Make	MERCEDES
Model	C C220 CDI SPORT
Colour	Red
Year of manufacture	2007
Top speed	141 mph
0 - 60 mph	8.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2025-03-20
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	40
Total items failed	7

MOT #18		2024-02-21 17:09
MOT test	number	400593494763
Result		✓ Passed
Next exp	ry date	2025-03-20
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Minor	Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated	l (5.3.4 (b) (i))
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (c	d) (ii))
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Steering rack has slight free play detected at steering who	eel (2.3 (a) (i))
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excess	sive movement (5.3.4 (a)
Advice	Nearside Rear Shock absorbers has slight external damage to the casing	corroded (5.3.2 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/13



MOT test number

Result

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front fog light bulb not working

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #16 2023-03-14 14:30 **MOT** test number 784453762514 Result × Failed **Advice** Nearside Front fog light bulb not working Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Offside Front Lower Suspension arm damaged and seriously weakened (5.3.3 (b) (i)) Advice Front Oil leak, but not excessive (8.4.1 (a) (i)) Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice**

MOT test number

Result

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/13



MOT #14 2022-03-21 12:43 **MOT** test number 168562125262 Result × Failed **Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g)) Fail Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

 MOT #13
 2021-02-08 15:19

 MOT test number
 917483810218

 Result
 ✓ Passed

 MOT #12
 2019-06-13 15:18

 MOT test number
 416033697261

 Result
 ✓ Passed

 Advice
 Nearside Rear hand brake lazy

MOT #11 2018-06-28 11:58 **MOT** test number 992872691131 Result ✓ Passed **MOT #10** 2018-06-28 11:58 651393325270 **MOT** test number Result × Failed Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/13



MOT #9 2017-11-01 11:47

MOT test number 419064793652

MOT #8 2017-10-27 11:44

MOT test number 113095972102

Result X Failed

Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

MOT #7 2016-11-03 14:18

MOT test number 819102795675

Result \(\sqrt{Passed} \)

Advice Offside Front tyre bald on edges

Advice Offside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front tyre bald on edges

Advice Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-11-05 12:34

MOT test number 865693921115

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-11-08 12:19 **MOT** test number 465772913413 Result ✓ Passed **MOT** #3 2012-12-05 12:17 **MOT test number** 238880842331 Result Passed **MOT #2** 2011-12-05 15:07 **MOT** test number 818339831332 Result Passed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-12-06 14:43
MOT test number	182230740340
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



More info >

Owner history

*		
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.		

	More info >	
Plate changes		
See in this check if this MERCEDES had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-06
Last registration	2024-02-21
Complete history	See info



Registration #1	2007-12-06	14 mi
Registration #2	2010-12-06	21.755 mi
Registration #3	2011-12-05	29.140 mi
Registration #4	2012-12-05	35.345 mi
Registration #5	2013-11-08	41.421 mi
Registration #6	2014-11-06	47.385 mi
Registration #7	2015-11-05	53.098 mi
Registration #8	2016-11-03	60.814 mi
Registration #9	2017-10-27	67.373 mi
Registration #10	2017-11-01	67.373 mi
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.117 es
Registration #14		11.117 es
Registration #15		
Registration #16		11.777 46
		11.777 es
Registration #16		11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64681130120655

CarCheck.co.uk page 13/13