



**HNI3FRF**

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO POP
Colour	Blue
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-17
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-22
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	28
Total items failed	4

## MOT #11 2024-02-21 09:28

MOT test number 677806172048

Result ✓ Passed

Next expiry date 2025-02-22

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

## MOT #10 2023-02-09 10:46

MOT test number 277267781601

Result ✓ Passed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #9** 2022-02-17 16:56**MOT test number** 453068559490**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 175/65/15 (5.2.3 (e))**MOT #8** 2022-02-17 11:30**MOT test number** 404150666512**Result** ✗ Failed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 175/65/15 (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2021-02-01 12:20**MOT test number** 495880461027**Result** ✓ Passed

**MOT #6** 2020-01-25 09:15**MOT test number** 973904189888**Result** ✓ Passed**MOT #5** 2019-02-23 09:41**MOT test number** 605765621976**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear exhaust box rusty

**MOT #4** 2018-02-10 11:04**MOT test number** 337856020172**Result** ✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Exhaust box outer skin deteriorating

**MOT #3** 2018-02-10 10:02**MOT test number** 665043480815**Result** ✗ Failed

- Advice** Nearside Front Nail in tyre
- Advice** Exhaust box outer skin deteriorating
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #2** 2017-02-17 14:17**MOT test number** 723175795747**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #1	2016-07-16 11:36
MOT test number	614664805969
Result	✓ Passed
Advice	Nail in n/s/r tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
22 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	22 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-31
Last registration	2024-02-21
Complete history	<a href="#">See info</a>



Registration #1	2013-07-31	12 mi
Registration #2	2016-07-16	68.454 mi
Registration #3	2017-02-17	73.689 mi
Registration #4	2018-02-10	70.527 mi
Registration #5	2018-02-10	78.753 mi
Registration #6	2019-02-23	83.503 mi
Registration #7	2020-01-25	88.697 mi
Registration #8	2020-05-20	95.277 mi
Registration #9	2020-05-20	95.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2020-05-20	95.277 mi
Registration #13	2020-05-20	95.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0596130