




report date: 2024-03-29

## General information

|                     |                         |
|---------------------|-------------------------|
| Make                | VAUXHALL                |
| Model               | ANTARA DIAMOND CDTI S/S |
| Colour              | White                   |
| Year of manufacture | 2016                    |
| Top speed           | 117 mph                 |
| Gearbox             | 6 speed Manual          |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 161 BHP             |
| Max. torque             | 350 Nm at 2.000 rpm |
| Engine capacity         | 2.231 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 52.3 mpg            |
| Consumption combined    | 44.1 mpg            |
| CO2 emission            | 167 g/km            |
| CO2 label               | H                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-01-08                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-02 |
| MOT pass rate      | 86 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 1          |
| Total advice items | 14         |
| Total items failed | 2          |

## MOT #7 2024-02-01 16:19

MOT test number 266647130083

Result ✓ Passed

Next expiry date 2025-02-02

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #6 2023-01-16 10:29

MOT test number 556308106523

Result ✓ Passed**Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

**MOT #5** 2022-01-06 11:23**MOT test number** 302279179231**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #4** 2021-02-03 14:57**MOT test number** 589065138779**Result** ✓ Passed**Advice** Chip in windscreen**MOT #3** 2020-06-17 09:04**MOT test number** 201749188875**Result** ✓ Passed**MOT #2** 2020-06-17 09:04**MOT test number** 690239440898**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2019-03-29 09:02**MOT test number** 575098204176**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
2 February 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 January           |
| <b>Days left</b>        | 246                             |
| <b>MOT expiry date</b>  | 2 February 2025                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | H          |
| <b>Single payment (12 months)</b>              | £ 290,00,- |
| <b>Single six month payment</b>                | £ 159,50,- |
| <b>Total payable by 12 monthly instalments</b> | £ 304,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>VO16NMJ</b> |
| Plate since          | 2019-06-29   |
| Current registration |  <b>VO16NMJ</b> |
| Plate since          | 2019-06-29   |

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 9                        |
| First mileage registration | 2016-03-31               |
| Last registration          | 2024-02-01               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2016-03-31 | 16 mi     |
| Registration #2 | 2019-03-29 | 7.851 mi  |
| Registration #3 | 2020-06-17 | 22.254 mi |
| Registration #4 | 2020-06-17 | 22.254 mi |
| Registration #5 | 2021-02-03 | 31.615 mi |
| Registration #6 | 2022-05-20 | 35.277 mi |
| Registration #7 | 2022-05-20 | 35.277 mi |
| Registration #8 | 2022-05-20 | 35.277 mi |
| Registration #9 | 2024-02-01 | 35.277 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 86%                             |
| Children       | 84%                             |
| Pedestrian     | 83%                             |
| Safety systems | 75%                             |
| Overall rating | 83%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2085 mm |
| Height              | 1761 mm |
| Length              | 4596 mm |
| Wheel base          | 2707 mm |
| Kerb weight         | 1836 kg |
| Max. allowed weight | 2479 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 65 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | Z22D1-51410125   |