





report date: 2024-03-28

### General information

Make	FORD
Model	FUSION FUSION +
Colour	Black
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date 2021-06-11

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-06

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-02-11
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	17
Total items failed	11

MOT #20		2024-02-12 18:01
MOT test n	umber	518773859375
Result		✓ Passed
Next expiry	date	2025-02-11
Advice Front Registration plate deteriorated but not likely to be misread delaminating and cracked (0.1 (b))		
Advice	Advise handbrake just efficient on minimum 16%	
Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt twisted and rubber under stress (2.1.3 (g) (i))		

MOT #19	2024-02-12 12:04
MOT test number	297623082012
Result	<b>×</b> Failed
Advice Front Registration plate deteriorated but not likely to be misread delamina (b))	ating and cracked (0.1
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the in and rubber under stress (2.1.3 (g) (i))	gress of dirt twisted

MOT #18	2023-03-14 16:10
MOT test number	578696610189
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #17** 2023-03-14 09:51

**MOT test number** 636414937872

Result

**X** Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #16** 2022-03-01 14:09

MOT test number 948139488277

Result \( \sqrt{Passed} \)

MOT #15 2022-03-01 10:51

**MOT test number** 864650634224

**Result** X Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Front Wheel bearing has excessive play (5.1.3 (a) (i))

**Fail** Offside Front Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #14** 2021-03-22 15:36

MOT test number 589958303073

**Advice** 

Nearside Front Play in steering rack inner joint(s)

**Advice** 

Offside Front Steering rack boot slightly twisted

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number 608588888339

Result X Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail** Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Both side (6.1.7 (g) (ii))

Fail Offside Rear All direction indicators not working (4.4.1 (a) (ii))

**Advice** Nearside Front Play in steering rack inner joint(s)

Advice Offside Front Steering rack boot slightly twisted

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12	2020-06-10 10:59

**MOT test number** 941679229739

**Result** ✓ Passed

MOT test number 599073149382

Result 

Passed

**MOT #10** 2018-06-07 10:06

**MOT test number** 118096262449

**Result** 
✓ Passed

MOT #9 2017-06-07 13:44

**MOT test number** 303257849658

Result \rightarrow Passed

CarCheck.co.uk page 5/14



Result

EO57LCY report date: 2024-03-28

Passed

MOT #8 2017-06-06 13:56

**MOT test number** 255810272101

Result X Failed

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #7 2016-06-17 10:56

MOT test number 460030920422

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #6 2015-06-24 15:56

**MOT test number** 299165275123

**Result** ✓ Passed

MOT #5 2014-07-29 16:25

**MOT test number** 569300314292

**Result** ✓ Passed

**MOT #4** 2012-09-11 09:25

MOT test number 536515652277

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Coolant leak on engine

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #3		2011-09-10 10:01
MOT test	number	428553251212
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2010-09-15 14:13
MOT test number	300148950417
Result	✓ Passed
MOT #1	2010-08-18 09:23
MOT test number	484730630296
Result	✓ Passed

CarCheck.co.uk page 7/14



#### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	11 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner history		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?
**************************************		
***************************************		
THE STREET STREE		
********		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-09-15
Last registration	2024-02-12
Complete history	See info



Registration #2       2010-08-18       22.391         Registration #3       2010-09-15       22.726         Registration #4       2011-09-10       24.901         Registration #5       2012-09-11       26.929         Registration #6       2014-07-29       27.964         Registration #7       2015-06-24       28.675         Registration #8       2016-06-17       44.441         Registration #9       2017-06-06       60.581         Registration #10       2017-06-07       60.581         Registration #11       2018-06-07       73.711			
Registration #3       2010-09-15       22.726         Registration #4       2011-09-10       24.901         Registration #5       2012-09-11       26.929         Registration #6       2014-07-29       27.964         Registration #7       2015-06-24       28.675         Registration #8       2016-06-17       44.441         Registration #9       2017-06-06       60.581         Registration #10       2017-06-07       60.581         Registration #11       2018-06-07       73.711         Registration #12       2019-06-07       86.322         Registration #14       Registration #15         Registration #16       Registration #17         Registration #18       Registration #20         Registration #20       Registration #21         Registration #22       Registration #22	Registration #1	2007-09-15	25 mi
Registration #4       2011-09-10       24.901         Registration #5       2012-09-11       26.929         Registration #6       2014-07-29       27.964         Registration #7       2015-06-24       28.675         Registration #8       2016-06-17       44.441         Registration #9       2017-06-06       60.581         Registration #10       2017-06-07       60.581         Registration #11       2018-06-07       73.711         Registration #12       2019-06-07       86.322         Registration #14       Registration #15         Registration #16       Registration #16         Registration #18       Registration #20         Registration #21       Registration #21         Registration #22       Registration #22	Registration #2	2010-08-18	22.391 mi
Registration #5 2012-09-11 26.929 Registration #6 2014-07-29 27.964 Registration #7 2015-06-24 28.675 Registration #8 2016-06-17 44.441 Registration #9 2017-06-06 60.581 Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #3	2010-09-15	22.726 mi
Registration #6 2014-07-29 27.964 Registration #7 2015-06-24 28.675 Registration #8 2016-06-17 44.441 Registration #9 2017-06-06 60.581 Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #4	2011-09-10	24.901 mi
Registration #7 2015-06-24 28.675 Registration #8 2016-06-17 44.441 Registration #9 2017-06-06 60.581 Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #5	2012-09-11	26.929 mi
Registration #8 2016-06-17 44.441 Registration #9 2017-06-06 60.581 Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #6	2014-07-29	27.964 mi
Registration #9 2017-06-06 60.581 Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #7	2015-06-24	28.675 mi
Registration #10 2017-06-07 60.581 Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #8	2016-06-17	44.441 mi
Registration #11 2018-06-07 73.711 Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #9	2017-06-06	60.581 mi
Registration #12 2019-06-07 86.322 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #10	2017-06-07	60.581 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #11	2018-06-07	73.711 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #12	2019-06-07	86.322 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #13		11.777 es
Registration #15 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #14		71.777 es
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #15		71.777 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #16		77,777 46
Registration #19 Registration #20 Registration #21 Registration #22	Registration #17		11.777 es
Registration #20 Registration #21 Registration #22	Registration #18		77,777 46
Registration #21 Registration #22	Registration #19		71.777 es
Registration #22	Registration #20		11.777 es
-	Registration #21		11.727 es
Registration #23	Registration #22		11.777 es
	Registration #23		11.777 esi

More info >

CarCheck.co.uk page 13/14



### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1175 kg
Max. allowed weight	1670 kg

# Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 14/14

Number of axles 2

**Engine number** 7L62605