



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 AIRPLAY PLUS
Colour	Black
Year of manufacture	2007
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-13
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-03
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	17
Total items failed	20

MOT #20	2023-12-04 10:40
MOT test number	843752573453
Result	✓ Passed
Next expiry date	2024-12-03

MOT #19	2023-11-21 11:48
MOT test number	503516255026
Result	✗ Failed

- Fail

Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail

Windscreen washer not working (3.5 (a))
- Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail

Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail

Nearside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

**MOT #18**

2022-10-08 16:34

**MOT test number**

951781300134

**Result**

✓ Passed

**Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #17**

2022-10-08 11:48

**MOT test number**

281868431508

**Result**

✗ Failed

**Fail** Central Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Central Front Windscreen washer not working (3.5 (a))**MOT #16**

2021-09-11 10:52

**MOT test number**

447902362706

**Result**

✓ Passed

**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #15** 2021-09-11 09:02**MOT test number** 153355578237**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))**MOT #14** 2020-09-12 09:42**MOT test number** 787596569648**Result** ✓ Passed**MOT #13** 2019-09-24 16:19**MOT test number** 820394911759**Result** ✓ Passed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #12** 2019-09-24 12:14**MOT test number** 870902921789**Result** ✗ Failed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11** 2018-08-30 15:53**MOT test number** 114965060138**Result** ✓ Passed

**MOT #10** 2018-08-25 11:20**MOT test number** 553835364026**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #9** 2017-08-21 16:34**MOT test number** 479918373959**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Oil leak**Advice** Both rear tyres cracking**MOT #8** 2016-08-22 15:15**MOT test number** 273474772913**Result** ✓ Passed**MOT #7** 2015-08-27 10:21**MOT test number** 891953851632**Result** ✓ Passed**MOT #6** 2015-08-27 10:21**MOT test number** 183478189856**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too high (1.8)

**MOT #5** 2014-08-29 14:21**MOT test number** 697021544237**Result** ✓ Passed**MOT #4** 2013-08-10 12:21**MOT test number** 715002223222**Result** ✓ Passed**MOT #3** 2012-08-23 10:24**MOT test number** 359686232264**Result** ✓ Passed**MOT #2** 2011-08-31 12:50**MOT test number** 546783941225**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2010-06-08 10:58**MOT test number** 193919350105**Result** ✓ Passed**Notice** Tyres all round getting low



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
3 December 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	3 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>KK07VXA</b>
Plate since	2019-03-29
Current registration	<b>KK07VXA</b>
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-29
Last registration	2023-12-04
Complete history	<a href="#">See info</a>



Registration #1	2007-06-29	26 mi
Registration #2	2010-06-08	28.270 mi
Registration #3	2011-08-31	35.473 mi
Registration #4	2012-08-23	39.281 mi
Registration #5	2013-08-10	47.167 mi
Registration #6	2014-08-29	52.452 mi
Registration #7	2015-08-27	55.743 mi
Registration #8	2015-08-27	55.743 mi
Registration #9	2016-08-22	57.241 mi
Registration #10	2017-08-21	58.844 mi
Registration #11	2018-08-25	61.211 mi
Registration #12	2019-08-29	62.557 mi
Registration #13	2020-08-29	63.557 mi
Registration #14	2021-08-29	64.557 mi
Registration #15	2022-08-29	65.557 mi
Registration #16	2023-08-29	66.557 mi
Registration #17	2024-08-29	67.557 mi
Registration #18	2025-08-29	68.557 mi
Registration #19	2026-08-29	69.557 mi
Registration #20	2027-08-29	70.557 mi
Registration #21	2028-08-29	71.557 mi
Registration #22	2029-08-29	72.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W4926126