





report date: 2024-03-29

### General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



## Internet history

#### Entry 3

Date	2023-08-22
Pictures	0

Listing price <u>View report</u>

### source: carcraft.co.uk

#### Entry 2

Listing price

Date	2023-08-17
Pictures	26

View report









#### source: cargurus.co.uk

#### Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-07-20
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #8		2023-06-23 09:31
MOT test	number	276863900607
Result		✓ Passed
Next expi	ry date	2024-07-20
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2022-07-06 08:50
MOT test	number 849914737899
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.1mm lowest point (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2.4mm lowest point (5.2.3 (e))

MOT #6	2021-07-02 10:33
MOT test number	854257271124
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT test number
977796633030

Result
Minor Front Windscreen wiper blade defective Nearside & Offside. Streaking (3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))

 MOT #3
 2018-07-21 13:26

 MOT test number
 593404037230

 Result
 ✓ Passed

MOT #2

MOT test number

Result

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1

MOT test number

298636389237

Result

Advice Front tyres worn on shoulders.

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



_	
<b></b>	history
IMMAR	

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
**************************************	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-08-09
Last registration	2023-06-23
Complete history	See info



Registration #1	2014-08-09	29 mi
Registration #2	2017-08-28	10.258 mi
Registration #3	2018-07-21	14.702 mi
Registration #4	2018-07-21	14.702 mi
Registration #5	2019-07-13	16.687 mi
Registration #6	2020-07-10	18.518 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.77 44

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



# Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

## Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073

CarCheck.co.uk page 11/11