





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2008
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-25

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2025-02-19
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	21
Total items failed	12


MOT #18		2024-02-14 10:21
MOT test	number	287389104389
Result		✓ Passed
Next expi	ry date	2025-02-19
Advice	Parking brake travel is high but not coming to the stop	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #17		2023-02-17 13:36
MOT test	number	721012860821
Result		✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Handbrake high but not to stop	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-28



MOT #15		2022-02-16 11:07
MOT test	number	550136811080
Result		✓ Passed
Advice Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (Rear axel and shock absorber casings have areas of minor corrosion	5.3.3 (b) (i))

CarCheck.co.uk page 4/14



Fail

SD08ZUC

report date: 2024-03-28

MOT test number

234682519556

Result

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting sill corroded (6.2.2 (d) (i))

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

MOT test number

212080112151

Result

✓ Passed

MOT test number

2019-03-28 15:48

MOT test number

195829574554

Result

✓ Pass with rectification

Front Windscreen washer provides insufficient washer liquid (3.5 (a))

 MOT #10
 2018-04-05 08:33

 MOT test number
 842309105721

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9		2017-04-03 09:24
MOT test number		344014230360
Result		✓ Passed
MOT #8		2017-04-03 09:24
MOT test number		665080614031
Result		× Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	

MOT #7	2016-04-04 09:17
MOT test number	412704499321
Result	✓ Passed
Advice Slight blow from exhaust flexi section	

MOT #6	2015-04-07 17:09
MOT test number	327037295051
Result	✓ Passed
MOT #5	2015-03-31 14:40
MOT test number	857660095071
Result	★ Failed
Fail Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	
Fail Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	

MOT #4	2014-03-31 16:07
MOT test number	556400094050
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

 MOT #3
 2013-03-22 11:05

 MOT test number
 415661583067

 Result
 ✓ Passed

 MOT #2
 2012-03-22 11:44

 MOT test number
 247792882032

 Result
 ✓ Passed

MOT #1	2011-04-15 12:56
MOT test number	147845601170
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



SD08ZUC report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-22
Last registration	2024-02-14
Complete history	See info



Registration #1	2008-04-22	17 mi
Registration #2	2011-04-15	20.448 mi
Registration #3	2012-03-22	27.851 mi
Registration #4	2013-03-22	34.899 mi
Registration #5	2014-03-31	39.412 mi
Registration #6	2015-03-31	41.821 mi
Registration #7	2015-04-07	41.828 mi
Registration #8	2016-04-04	44.276 mi
Registration #9	2017-04-03	46.628 mi
Registration #10	2017-04-03	46.628 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es

More info >

CarCheck.co.uk page 13/14



SD08ZUC report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack caluk	page 14/14

CarCheck.co.uk page 14/14

Number of seats	4
Number of axles	2
Engine number	BMD 373294