





report date: 2024-03-28

General information

Make	HONDA
Model	CR-V I-DTEC SR
Colour	Grey
Year of manufacture	2015
Top speed	122 mph
0 - 60 mph	10.2 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	158 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2022-01-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2022-01-10
------	------------

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

D. L.	2021 01 21
Date	2021-01-31

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



✓ Passed

MOT history

Result

MOT expiry date	2025-03-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	18
Total items failed	2

MOT #7		2024-03-25 13:39
MOT test	number	588471593035
Result		✓ Passed
Next expi	ry date	2025-03-24
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2023-01-21 10:36
MOT test number	838822237852
Result	✓ Passed
MOT #5	2022-01-21 15:28
MOT test number	633364991196

CarCheck.co.uk page 3/12



NJ65USD

report date: 2024-03-28

MOT test number
926930843316

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Nail in tyre

Advice Items removed from driver's view prior to test Dash cam

MOT #3 2020-08-17 10:47 **MOT** test number 314595512834 Result × Failed Nearside Rear Nail in tyre **Advice Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail **Advice** Items removed from driver's view prior to test Dash cam Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2		2019-08-20 08:37
MOT test	number	240520395253
Result		✓ Passed
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Child Seat fitted not allowing full inspection of adult belt x2	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



MOT #1 2018-08-30 09:45

MOT test number 918389685692

Result ✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Nail in tyre

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	NK NY
Plate since	
Current registration	NK NK
Flate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-14
Last registration	2024-03-25
Complete history	See info



Registration #1	2015-09-14	18 mi
Registration #2	2018-08-30	40.710 mi
Registration #3	2019-08-20	53.041 mi
Registration #4	2020-08-17	67.390 mi
Registration #5	2020-08-17	67.390 mi
Registration #6		11.777 es
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		D.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1685 mm
Length	4605 mm
Wheel base	2630 mm
Kerb weight	1724 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A41015776

CarCheck.co.uk page 12/12