




report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR 16V
Colour	Silver
Year of manufacture	2006
Top speed	131 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 2

Date	2023-01-27
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	18
Total items failed	19

MOT #22	2023-12-14 12:14
MOT test number	653389863429
Result	✓ Passed
Next expiry date	2024-12-21
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #21**

2023-12-12 16:54

MOT test number

978648397249

Result**✗ Failed****Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #20**

2022-12-22 14:25

MOT test number

450710672224

Result**✓ Passed**

**MOT #19**

2022-04-22 14:48

MOT test number

920623780324

Result

✗ Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Broken wiring hanging from sensor**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure Tyre cracked to the point where the cords are showing. Tyre is 16 years old (5.2.3 (d) (ii))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Parking brake inoperative on one side (1.4.1 (a))**MOT #18**

2021-02-13 09:23

MOT test number

817991933213

Result

✓ Passed

MOT #17

2020-03-03 14:44

MOT test number

966604105232

Result

✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #16**

2019-02-18 10:44

MOT test number

521832821048

Result

✓ Passed

**MOT #15** 2018-02-21 11:26**MOT test number** 431462486736**Result** Passed**MOT #14** 2018-02-20 11:01**MOT test number** 777810462626**Result** Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #13** 2017-02-13 16:55**MOT test number** 417986295292**Result** Passed**MOT #12** 2017-02-13 11:28**MOT test number** 997905903393**Result** Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Front brake drum in such a condition that it is seriously weakened (3.5.1i)**MOT #11** 2016-02-22 10:37**MOT test number** 194785786232**Result** Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)

**MOT #10** 2015-02-20 16:46**MOT test number** 879391655065**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #9** 2015-02-20 11:43**MOT test number** 128511555490**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2014-02-25 15:15**MOT test number** 475276354063**Result** ✓ Passed**MOT #7** 2013-02-27 12:05**MOT test number** 636028653056**Result** ✓ Passed**MOT #6** 2012-03-05 12:29**MOT test number** 517875562086**Result** ✓ Passed**MOT #5** 2011-02-18 11:18**MOT test number** 355059941085**Result** ✓ Passed



MOT #4	2011-02-18 11:18
MOT test number	549139941010
Result	✗ Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #3	2010-02-22 11:14
MOT test number	211203150023
Result	✓ Passed

MOT #2	2009-03-10 10:24
MOT test number	420989869090
Result	✓ Passed

MOT #1	2009-03-10 10:24
MOT test number	862409369098
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
21 December 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-10
Last registration	2023-12-14
Complete history	See info



Registration #1	2006-03-10	7 mi
Registration #2	2009-03-10	19.223 mi
Registration #3	2010-02-22	25.103 mi
Registration #4	2011-02-18	33.161 mi
Registration #5	2012-03-05	41.520 mi
Registration #6	2013-02-27	48.190 mi
Registration #7	2014-02-25	55.721 mi
Registration #8	2015-02-20	61.145 mi
Registration #9	2015-02-20	61.145 mi
Registration #10	2016-02-22	66.586 mi
Registration #11	2017-02-13	71.159 mi
Registration #12	2018-02-22	75.277 mi
Registration #13	2019-02-22	79.277 mi
Registration #14	2020-02-22	83.277 mi
Registration #15	2021-02-22	87.277 mi
Registration #16	2022-02-22	91.277 mi
Registration #17	2023-02-22	95.277 mi
Registration #18	2023-02-22	95.277 mi
Registration #19	2023-02-22	95.277 mi
Registration #20	2023-02-22	95.277 mi
Registration #21	2023-02-22	95.277 mi
Registration #22	2023-02-22	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1475 mm
Length	4745 mm
Wheel base	2750 mm
Kerb weight	1394 kg
Max. allowed weight	1914 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4P1430232