



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER
Colour	Red
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #11	2024-01-31 11:41
MOT test number	784471961993
Result	✓ Passed
Next expiry date	2025-02-01
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2023-01-20 10:58
MOT test number	211049413984
Result	✓ Passed
Advice	Nearside Front Upper Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Run flat and conventional tyres can be mixed on the same axle, although this is not recommended.
Advice	Central Front TPMS light on low pressure
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9	2022-01-24 14:57
MOT test number	261777418430
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #8** 2021-02-02 16:03**MOT test number** 784078975999**Result** ✓ Passed**MOT #7** 2020-05-20 09:21**MOT test number** 205042673171**Result** ✓ Passed**MOT #6** 2019-03-14 10:20**MOT test number** 230488528909**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2018-03-20 14:13**MOT test number** 480234955776**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2018-03-20 14:13**MOT test number** 366507584826**Result** ✗ Failed**Pass with rectification** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2017-04-18 09:03**MOT test number** 948688520510**Result** ✓ Passed



MOT #2	2016-04-21 14:23
MOT test number	265530352388
Result	✓ Passed
MOT #1	2015-04-28 12:12
MOT test number	838638015152
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-14
Last registration	2024-01-31
Complete history	See info



Registration #1	2012-06-14	11 mi
Registration #2	2015-04-28	27.024 mi
Registration #3	2016-04-21	39.084 mi
Registration #4	2017-04-18	52.612 mi
Registration #5	2018-03-20	66.272 mi
Registration #6	2018-03-20	66.272 mi
Registration #7	2019-03-14	79.094 mi
Registration #8	2019-03-20	91.272 mi
Registration #9	2019-03-20	91.272 mi
Registration #10	2019-03-20	91.272 mi
Registration #11	2019-03-20	91.272 mi
Registration #12	2019-03-20	91.272 mi
Registration #13	2019-03-20	91.272 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	B081J342