





General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 DCB
Colour	Black
Year of manufacture	2009
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	32.9 mpg
Consumption combined	28.8 mpg






Internet history

Entry 5	
Date	2022-02-18
Pictures	12
Listing price	<u>View report</u>




source: autotrader.co.uk

Entry 4	
Date	2022-01-09
Pictures	12
Listing price	View report



source: autotrader.co.uk

Entry 3	
Date	2021-09-22
Pictures	12
Listing price	View report



source: autotrader.co.uk

Pictures

Listing price

12

View report



source: autotrader.co.uk

Entry 1	
Date	2021-06-19
Pictures	12
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-22
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	23
Total items failed	21

МОТ #20	2023-05-11 11:24
MOT test number	763409681668
Result	✓ Passed
Next expiry date	2024-05-22
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Underside corrision	

MOT #19	2023-05-10 11:39
MOT test number	459654524358
Result	🗙 Failed
Advice Underside corrision	
Fail Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #18	2022-05-23 11:56
MOT test number	422631991029
Result	✓ Passed



Ρ	Ν	5	9	k		Η	0	
1	repo	ort d	date	e: 1	20	24-()3-2	8

MOT #17	2022-05-17 12:11
MOT test number	832634585945
Result	🗙 Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Front Prop shaft joint excessively worn rear joint (6.1.7 (c) (i))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2021-11-12 12:16
MOT test number	580003909749
Result	✓ Passed
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamp	os or light sources (4.7.1
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #15	2021-10-18 11:49
MOT test number	847093565861
Result	🗙 Failed
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2	2 (c))
Minor Nearside Rear Registration plate lamp throwing direct white light to the rear (4	ł.7.1 (a))
Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Fail Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))	



MOT #14	2020-09-	-15 10:19
MOT test	number 98636	6658434
Result		🗸 Passed
Advice Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i)) Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect $(5.3.2 (b))$	

MOT #13	2020-09-08 10:48
MOT test number	225728529426
Result	🗙 Failed
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))

MOT #12		2019-09-10 11:27
MOT test	number	224696007835
Result		✓ Passed
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Prop shaft joint worn, but not excessively transfer box (6.1.7 (c) (i))	

MOT #11	2018-08-28 14:04
MOT test number	503003927726
Result	🗸 Passed
Advice Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))	



MOT #10		2018-08-28 09:02
MOT test number		187197349270
Result		🗙 Failed
Advice Nearside Front C	Duter Track rod end ball joint has slight play (2.1.3 (b) (i))	
Pass with rectification	Rear Reversing lamp inoperative (4.6.1 (a))	

MOT #9	2017-09-14 12:49
MOT test number	194801098839
Result	✓ Passed

MOT #8	8	2017-08-23 10:32
MOT te	est number	269996376041
Result		🗙 Failed
Fail	Nearside Registration plate lamp shows direct white light to the rear (1.1.C.1f)	
Fail	Supplementary Restraint System warning lamp indicates a fault (5.4.2)	

MOT #7	2016-09-08 15:20
MOT test number	101870987786
Result	✓ Passed
Advice Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)	



MOT #6	2016-08-31 09:36
MOT test number	863076662149
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Advice Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #5	2015-09-08 15:00
MOT test number	131468894507
Result	✓ Passed

МОТ #4	2015-09-07 09:08
MOT test number	532170317575
Result	🗙 Failed
Fail Centre Rear Upper Stop lamp not working (1.2.1b)Fail Front Exhaust has a major leak of exhaust gases (7.1.2)	

MOT #3	2014-08-20 11:42
MOT test number	685582334242
Result	✓ Passed
MOT #2	2013-08-21 15:16

2013-00-21 13.10
768933933283
✓ Passed





MOT #1	2012-08-08 11:44
MOT test number	429591022211
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
	E Stand
Date	N. Sterring and a start of the
Category	ame
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



Mileage check

In miles
26
2009-09-03
2023-05-11
<u>See info</u>



Registration #1	2009-09-03	20 mi
Registration #2	2012-08-08	17.626 mi
Registration #3	2013-08-21	23.160 mi
Registration #4	2014-08-20	28.488 mi
Registration #5	2015-09-07	34.385 mi
Registration #6	2015-09-08	34.385 mi
Registration #7	2016-08-31	38.879 mi
Registration #8	2016-09-08	38.879 mi
Registration #9	2017-08-23	45.261 mi
Registration #10	2017-09-14	45.333 mi
Registration #11	2018-08-28	50.077 mi
Registration #12	2018-08-28	50.078 mi
Registration #13	2019-09-10	54.248 mi
Registration #14		11.117 est
Registration #15		11.117 esi
Registration #16		11.117 est
Registration #17		11.117 esi
Registration #18		11.117 est
Registration #19		11.117 esi
Registration #20		11.117 est
Registration #21		11.117 mi
Registration #22		11.117 est
Registration #23		11.117 mi
Registration #24		10.207 mi
Registration #25		11.777 mi
Registration #26		10.207 mi
		DOC: - 14/15

CarCheck.co.uk

More info >





Car features

S0225	Air conditioning
S0295	
50482	
50501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	634755