



report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 2 SW
Colour	Silver
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	255 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-01-21
Pictures	45
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-01-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #15	2024-01-24 17:31
MOT test number	524692029102
Result	✓ Passed
Next expiry date	2025-01-28
<b>Advice</b>	Suspension component corroded but not seriously weakened All front and rear (5.3.3 (b) (i))
<b>Minor</b>	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Slight seepage (6.1.7 (g) (i))

MOT #14	2023-01-25 12:13
MOT test number	808888854166
Result	✓ Passed
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2022-01-26 08:37
MOT test number	465176131514
Result	✓ Passed
<b>Advice</b>	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2021-01-29 16:40**MOT test number** 390843378414**Result** ✓ Passed**MOT #11** 2021-01-27 17:13**MOT test number** 824766309605**Result** ✗ Failed**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #10** 2020-06-18 07:53**MOT test number** 271469095544**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded and pitted on inner face (1.1.14 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2019-06-19 08:17**MOT test number** 709510748986**Result** ✓ Passed**MOT #8** 2018-11-24 16:34**MOT test number** 551160162544**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm front bush (5.3.4 (a) (i))

**MOT #7**

2018-11-24 10:20

**MOT test number**

795335203353

**Result**

✗ Failed

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge 2.5 mm (5.2.3 (e))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm front bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge 1.8 mm (5.2.3 (e))**MOT #6**

2017-11-14 11:05

**MOT test number**

238254289089

**Result**

✓ Passed

**Advice** N/s/r tyre perished**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Front bush (2.4.G.2)**Advice** N/s/f steering rack gaitor clip loose, but gaitor still secure to housing**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Both rear brake pads wearing thin. Unable to clearly inspect due to caliper set up obscuring view**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #5**

2016-11-25 11:54

**MOT test number**

772312571151

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2016-11-25 08:50**MOT test number** 726084794485**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-11-11 14:47**MOT test number** 121206644475**Result** ✓ Passed**MOT #2** 2015-06-30 11:32**MOT test number** 859581785176**Result** ✓ Passed**MOT #1** 2015-06-30 11:32**MOT test number** 255481785102**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
28 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	28 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>FW12LJY</b>
Plate since	2019-03-28
Current registration	<b>FW12LJY</b>
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-08-29
Last registration	2024-01-24
Complete history	<a href="#">See info</a>



Registration #1	2012-08-29	14 mi
Registration #2	2015-06-30	28.585 mi
Registration #3	2015-11-11	31.572 mi
Registration #4	2016-11-25	38.827 mi
Registration #5	2016-11-25	38.827 mi
Registration #6	2017-11-14	44.428 mi
Registration #7	2018-11-24	55.891 mi
Registration #8	2018-11-24	55.891 mi
Registration #9	2019-05-29	55.891 mi
Registration #10	2019-05-29	55.891 mi
Registration #11	2019-05-29	55.891 mi
Registration #12	2019-05-29	55.891 mi
Registration #13	2019-05-29	55.891 mi
Registration #14	2019-05-29	55.891 mi
Registration #15	2019-05-29	55.891 mi
Registration #16	2019-05-29	55.891 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1525 mm
Length	4490 mm
Wheel base	2650 mm
Kerb weight	1502 kg
Max. allowed weight	1920 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	D4FBCZ431445
---------------	--------------