



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Red
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-05
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	35
Total items failed	11

MOT #13 2023-11-14 09:22

MOT test number 814661107028

Result ✓ Passed

Next expiry date 2024-11-23

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm Tread (5.2.3 (e))

Advice Vehicle Body/Structure, Suspension Components & Prescribed Areas Corroded

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm Tread (5.2.3 (e))

Advice Offside Rear Bumper Damaged - No Sharp Edges

MOT #12 2022-11-16 12:56

MOT test number 337919799014

Result ✓ Passed

MOT #11 2021-11-24 13:49

MOT test number 113647228682

Result ✓ Passed

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2021-11-20 10:35

MOT test number

823257482591

Result**✗ Failed**

- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded 2x section (1.1.11 (c))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Rear Brake pipe excessively corroded 2x section (1.1.11 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9

2020-11-21 14:41

MOT test number

676344961390

Result**✓ Passed**

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #8**

2019-05-16 10:36

MOT test number

836206366631

Result

✓ Passed

- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7

2019-05-16 10:36

MOT test number

745881734003

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #6

2018-05-17 14:26

MOT test number

702146750745

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2018-05-17 08:05**MOT test number** 552414948392**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2017-05-13 08:26**MOT test number** 204609247750**Result** ✓ Passed**MOT #3** 2016-05-19 08:39**MOT test number** 315106168850**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Rear tyre has a nail in it**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2015-05-05 09:24
MOT test number	459915825194
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-05-08 09:41
MOT test number	305658524190
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	NU11KDF
Plate since	2019-03-28
Current registration	NU11KDF
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-10
Last registration	2023-11-14
Complete history	See info



Registration #1	2011-05-10	29 mi
Registration #2	2014-05-08	8.258 mi
Registration #3	2015-05-05	18.868 mi
Registration #4	2016-05-19	34.236 mi
Registration #5	2017-05-13	43.357 mi
Registration #6	2018-05-17	56.532 mi
Registration #7	2018-05-17	56.532 mi
Registration #8	2019-05-16	68.787 mi
Registration #9	2020-05-20	75.277 mi
Registration #10	2021-05-20	81.277 mi
Registration #11	2022-05-20	87.277 mi
Registration #12	2023-05-20	93.277 mi
Registration #13	2024-05-20	99.277 mi
Registration #14	2025-05-20	105.277 mi
Registration #15	2026-05-20	111.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225