





report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC ACTIVE
Colour	Blue
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history

Entry 1

Date 2021-09-10

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #10		2023-12-27 14:50
MOT test	number	157719142597
Result		✓ Passed
Next expi	ry date	2025-01-13
Advice	Rear BOTH REAR SHOCKERS CORRODED	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

MOT #9	2023-12-27 11:35
MOT test number	784006771943
Result	× Failed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively	(3.4 (b) (ii))
Advice Rear BOTH REAR SHOCKERS CORRODED	

MOT #8	2023-01-11 09:02
MOT test number	567085929878
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2022-01-14 14:07

MOT test number 252605284428

Result
✓ Passed

MOT #6 2022-01-13 12:24

MOT test number 608054309207

Result X Failed

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Brake pipe excessively corroded Front too Rear @ the Rear (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Brake pipe excessively corroded Front too Rear @ the Rear (1.1.11 (c))

MOT #5 2020-11-04 15:01

MOT test number 621458089515

Result \(\sqrt{Passed} \)

Minor Offside Rear Tyre obviously under inflated (5.2.3 (l))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #4 2019-11-14 13:11

MOT test number 213394569891

Result ✓ Passed

MOT #3 2018-08-21 14:03

MOT test number 914160263512

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)

Advice Brake pad(s) wearing thin both front (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Front bumper damage

MOT #1		2016-10-01 10:10
MOT test	number	866780149830
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	la : a b a
UWNEr	INISTARV
OWITCH	IIISCOLY

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-10
Last registration	2023-12-27
Complete history	See info



2013-12-10	19 mi
2016-10-01	22.899 mi
2017-08-04	31.072 mi
2018-08-21	37.044 mi
2019-11-14	44.555 mi
2020-11-04	48.142 mi
	11.777 es
	11.117 es
	11.177 es
	11.777 es
	11.177 es
	2016-10-01 2017-08-04 2018-08-21 2019-11-14

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Engine number

1ZRU592292