





## General information

Make	RENAULT	
Model	MASTER LM35 BUSINESS ENERGY DCI S/R P/V	
Colour	White	
Year of manufacture	2016	
Top speed	93 mph	
Gearbox	6 speed Manual	

# Engine & fuel consumption


Power	135 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	2.298 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	1





# Internet history

Entry 1	
Date	2021-07-19
Pictures	23
Listing price	View report









source: cargurus.co.uk



### MOT history

MOT expiry date	2025-01-09
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	17
Total items failed	2

MOT #6		2023-12-14 17:21
MOT test	number	710926112359
Result		🗸 Passed
Next expi	ry date	2025-01-09
<b>Advice</b> (a) (i))	Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in e	xcessive movement (5.3.4
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Advice</b> (a) (i))	Offside Front Inner Anti-roll bar pin or bush worn but not resulting in exc	cessive movement (5.3.4



mwl6FTX report date: 2024-03-28

MOT #5		2023-01-10 14:54
MOT test	number	782500116631
Result		✓ Passed
Advice	Offside Play in steering rack inner joint(s)	
Minor (i))	Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingr	ress of dirt (2.1.3 (g)
Advice	Offside Front Suspension arm ball joint has slight play STRONG ADVISORY (5.3	.4 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice STRONG A	Offside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive DVISORY (5.3.4 (a) (i))	movement d bush
Advice	Nearside Rear Nail in tyre inner edge of tread	
Advice	Nearside Front Suspension arm ball joint has slight play STRONG ADVISORY (5	.3.4 (a) (i))
Advice	Rear Inner Brake pad(s) wearing thin STRONG ADVISORY (1.1.13 (a) (ii))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice STRONG A	Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessiv DVISORY (5.3.4 (a) (i))	e movement d bush

MOT #4		2022-01-06 13:04
MOT test	number	137366868538
Result		✓ Passed
Advice	Front Lower Suspension arm ball joint has slight play 'Both sides' (5.3.4 (a) (i))	
Advice (a) (i)) Rear Anti-roll bar pin or bush worn but not resulting in excessive movement 'Both D bushes' (5.3.4		n D bushes' (5.3.4

MOT #3	2020-06-15 13:51
MOT test number	756015174693
Result	✓ Passed
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	





MOT #2	2020-06-11 10:29
MOT test number	318978730255
Result	🗙 Failed
<ul> <li>Fail Nearside Front Steering linkage ball joint worn to the extent there is a serious risk of track arm on rack (2.1.3 (b) (ii))</li> <li>Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))</li> <li>Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))</li> </ul>	of detachment
MOT #1	2019-06-18 15:19
MOT test number	443960704276

Result

✓ Passed



mwl6FTX report date: 2024-03-28

Tax & MOT check

√ Taxed	✓ MOT	
Tax due: 1 January 2025	Expires: 9 January 2025	
Tax status	Valid until 1 January	
Days left	247	
MOT expiry date	9 January 2025	
Full MOT history	See MOT history	

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
********	
NUMBER OF TAXABLE	
**********	
********	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-06-16
Last registration	2023-12-14
Complete history	See info



Registration #1	2016-06-16	26 mi
Registration #2	2019-06-18	108.862 mi
Registration #3	2020-06-11	130.800 mi
Registration #4	2020-06-15	130.802 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 est





#### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

## Dimensions & weight

Width	2470 mm
Height	2488 mm
Length	6198 mm
Wheel base	4332 mm
Kerb weight	1970 kg
Max. allowed weight	3500 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection

Number of seats	3
Number of axles	2
Engine number	C059927