



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R58) COOPER
Colour	Blue
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	116 BHP
Max. torque	150 Nm at 4.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 9

Date 2022-01-30

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 8

Date 2022-01-15

Pictures 10

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 7

Date 2022-01-01

Pictures 10

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 6

Date 2021-12-18

CarCheck.co.uk


Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

#### Entry 5

Date	2021-12-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

#### Entry 4

Date	2021-10-31
Pictures	10
Listing price	<a href="#">View report</a>




source: [autotrader.co.uk](https://www.autotrader.co.uk)

#### Entry 3

Date	2021-10-16
Pictures	10
Listing price	<a href="#">View report</a>






source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-10-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-18
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	38
Total items failed	17

MOT #18	2023-10-27 15:27
MOT test number	973797862123
Result	✓ Passed
Next expiry date	2024-10-26
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Steering rack has slight free play detected at steering wheel inner joint (2.3 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both front tries (5.2.3 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear trailer arm bush (5.3.4 (a) (i))

MOT #17	2023-10-26 09:36
MOT test number	295156128164
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn lower arm back bush (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Steering rack has slight free play detected at steering wheel inner joint (2.3 (a) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both front tries (5.2.3 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear trailer arm bush (5.3.4 (a) (i))

**MOT #16** 2022-03-15 15:46**MOT test number** 985562479009**Result** ✓ Passed**MOT #15** 2021-09-01 10:29**MOT test number** 136348947863**Result** ✓ Passed**MOT #14** 2021-08-24 08:03**MOT test number** 968529882665**Result** ✗ Failed

**Advice** Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2020-06-15 13:38**MOT test number** 953149534467**Result** ✓ Passed

**Advice** Oil leak, but not excessive slight leak from engine (8.4.1 (a) (i))

**MOT #12**

2020-06-08 14:20

**MOT test number**

304102819530

**Result****✗ Failed****Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Oil leak, but not excessive slight leak from engine (8.4.1 (a) (i))**Advice** Coolant leak engine running hotter than normal leaking coolant out of expansion tank**Advice** Offside Rear reverse lamp not working**Fail** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear reverse lamp not working**MOT #11**

2018-08-16 15:48

**MOT test number**

563867422104

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #10**

2018-08-16 08:40

**MOT test number**

694063044020

**Result****✗ Failed**

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9**

2017-07-20 14:38

**MOT test number**

548068341973

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Offside Rear reverse light not working
- Advice** Exhaust has a minor leak of exhaust gases rear silencer deteriorated (7.1.2)
- Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)



**MOT #8** 2017-07-20 09:34**MOT test number** 336919626371**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases rear silencer deteriorated (7.1.2)
- Advice** Offside Rear reverse light not working
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm low inner edge (4.1.E.1)

**MOT #7** 2016-07-05 13:24**MOT test number** 705905929363**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Oil leak
- Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**MOT #6** 2015-06-23 11:02**MOT test number** 739554975136**Result** ✓ Passed



<b>MOT #5</b>	2015-06-23 11:02
---------------	------------------

<b>MOT test number</b>	317934875151
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---

<b>Pass with rectification</b>	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

<b>MOT #4</b>	2014-08-08 17:47
---------------	------------------

<b>MOT test number</b>	708420224225
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-08-16 12:13
---------------	------------------

<b>MOT test number</b>	805418823283
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-01-14 10:04
---------------	------------------

<b>MOT test number</b>	658984112079
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2011-01-20 17:16
---------------	------------------

<b>MOT test number</b>	148250421027
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED


More info >





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-21
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2007-09-21	7 mi
Registration #2	2011-01-20	17.271 mi
Registration #3	2012-01-14	22.035 mi
Registration #4	2013-08-16	28.413 mi
Registration #5	2015-06-23	34.193 mi
Registration #6	2016-07-05	37.961 mi
Registration #7	2017-07-20	46.739 mi
Registration #8	2017-07-20	46.739 mi
Registration #9	2018-08-16	60.099 mi
Registration #10	2018-08-16	60.101 mi
Registration #11	2020-06-08	65.685 mi
Registration #12	2020-06-15	65.707 mi
Registration #13	2021-08-24	66.236 mi
Registration #14	2022-05-20	66.236 mi
Registration #15	2022-05-20	66.236 mi
Registration #16	2022-05-20	66.236 mi
Registration #17	2022-05-20	66.236 mi
Registration #18	2022-05-20	66.236 mi
Registration #19	2022-05-20	66.236 mi
Registration #20	2022-05-20	66.236 mi
Registration #21	2022-05-20	66.236 mi
Registration #22	2022-05-20	66.236 mi
Registration #23	2022-05-20	66.236 mi
Registration #24	2022-05-20	66.236 mi
Registration #25	2022-05-20	66.236 mi
Registration #26	2023-10-27	66.236 mi

**More info** >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1925 mm
Height	1415 mm
Length	3635 mm
Wheel base	2467 mm
Kerb weight	1250 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	D487Q460
---------------	----------