






report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2012
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-03

Pictures 2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-12-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	28
Total items failed	2

MOT #13	2023-11-30 10:06
MOT test number	230639704521
Result	✓ Passed
Next expiry date	2024-12-22
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2022-11-23 15:09
MOT test number	133987721553
Result	√ Passed

MOT #11	2022-11	-23 10:34
MOT test	number 98166	59926006
Result		X Failed
MAJOR	Offside Front Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Nearside Front Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a)))

MOT #10	2021-12-23 13:14
MOT test number	910804154954
Result	✓ Passed
Advice Offside Front tyre is winter type t.rated.	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9 2021-12-21 13:15

MOT test number 272427329888

Result X Failed

DANGEROUS Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Advice Offside Front tyre is winter type t.rated.

DANGEROUS Nearside Front Electrical wiring likely to touch hot or rotating parts brake pad warning light sensor wire rubbing on inside of wheel (4.11 (a) (iii))

Advice Nearside Front pad warning wire broken off rubbing on n/s/f wheel.

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement strut top mounting bearing rough (5.3.4 (a) (i))

MOT #8 2020-12-09 14:02

MOT test number 769875484671

Result \(\sqrt{Passed} \)

Advice Offside Front Upper strut bearing getting notchy when turning lock to lock

Advice Offside Front Lower Suspension arm ball joint has slight play very slight wear (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear exhaust getting very rusty

MOT #7 2019-11-28 10:49

MOT test number 653674780185

Advice Offside Front Tyre worn close to legal limit/worn on edge on limit very worn on inside edge (5.2.3

(e))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice
Rear exhaust getting very rusty but not blowing yet

Advice
Offside Rear Tyre slightly damaged/cracking or perishing perishing on side wall (5.2.3 (d) (ii))

Advice
Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))

Advice
Nearside Rear Tyre slightly damaged/cracking or perishing side wall perished (5.2.3 (d) (ii))

MOT #5

MOT test number

Result

Advice Rear exhaust silencer outer skin corroding

Advice Rear tyres perishing

MOT test number

688933446915

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear tyres perishing

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Rear exhaust silencer outer skin corroding

MOT #3

MOT test number

618298205584

Result

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear tyres starting to get perished on outer side walls

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

Fail Parking brake: efficiency below requirements (3.7.B.7)

Rear tyres starting to get perished on outer side walls

MOT #1 2015-11-23 17:55

MOT test number 338889632237

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

, ,		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-14
Last registration	2023-11-30
Complete history	See info



Registration #1	2012-12-14	14 mi
Registration #2	2015-11-23	25.374 mi
Registration #3	2016-11-24	30.751 mi
Registration #4	2016-11-24	30.751 mi
Registration #5	2017-11-15	37.585 mi
Registration #6	2017-11-15	37.587 mi
Registration #7	2018-11-26	51.999 mi
Registration #8	2019-11-28	66.134 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel delivery	Multi-Point Injection	Multi-Point Injection	
Number of doors	5		
Number of seats	5		
Engine number Carcheck.co.uk	0207966	page 13/13	