





report date: 2024-03-28

# General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date	2021-10-17
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-11
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #9	2023-07-05 14:32
MOT test number	261720182694
Result	✓ Passed
Next expiry date	2024-07-11

MOT #8	2022-07-12 13:53
MOT test number	437676167986
Result	✓ Passed

MOT #7	2022-07-12 13:53
MOT test number	437070334113
Result	<b>X</b> Failed

Pass with rectification

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #6	2021-01-18 10:58
MOT test number	523315205718
Result	<b>✓</b> Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #5** 2020-01-28 09:07

MOT test number 203233594812

**Result** ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

MOT #4 2019-01-18 12:31

MOT test number 923598202358

**Result** ✓ Passed

MOT #3 2019-01-18 09:35

**MOT test number** 629287777773

**Result** X Failed

MAJOR Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MOT #2** 2018-01-17 09:54

MOT test number 511305366512

Result 

Passed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Front Tyre worn close to the legal limit + worn devoid of tread on far inner edge (4.1.E.1)

**Advice** Offside Rear Shock absorber has a light misting of oil when fully extended (2.7.3)

Advice Nearside Front Tyre worn close to the legal limit + worn devoid of tread on far outer edge (4.1.E.1)

**Advice** Nearside Rear Shock absorber has a light misting of oil when fully extended (2.7.3)

CarCheck.co.uk page 4/12



report date: 2024-03-28

**MOT #1** 2018-01-17 09:54 633245799965 **MOT** test number Result **★** Failed **Pass with rectification** Nearside Stop lamp not working (1.2.1b) Pass with rectification Exhaust emits an excessive level of metered smoke (7.4.B.3a) Advice Offside Front Tyre worn close to the legal limit + worn devoid of tread on far inner edge (4.1.E.1) Advice Offside Rear Shock absorber has a light misting of oil when fully extended (2.7.3) Advice Parking brake lever has little reserve travel (3.1.6b) Advice Nearside Front Tyre worn close to the legal limit + worn devoid of tread on far outer edge (4.1.E.1) Nearside Rear Shock absorber has a light misting of oil when fully extended (2.7.3) Advice

CarCheck.co.uk page 5/12



report date: 2024-03-28

# Tax & MOT check



Tax status	valid until 1 july
Days left	63
MOT expiry date	11 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <a href="here">here</a> for the results.

### Damage 1

Date	
Category	
Tyne	

Damage 2	
Date	
Category	



### Extra VAUXHALL salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

# Owner history

owner motory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
*********	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	UK
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-02-05
Last registration	2023-07-05
Complete history	See info



Registration #1	2015-02-05	9 mi
Registration #2	2018-01-17	21.861 mi
Registration #3	2018-01-17	21.861 mi
Registration #4	2019-01-18	28.651 mi
Registration #5	2019-01-18	28.651 mi
Registration #6	2020-01-28	39.563 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10,100 mg

More info >

CarCheck.co.uk page 11/12



		_		
I ) I m	ension	c l	MOIG	nt.
	CHSIUH	3 W	welu	III.

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005688130 LN9

CarCheck.co.uk page 12/12