



General information

Make	MINI
Model	FIRST ONE
Colour	Silver
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-12-06
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-21
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	34
Total items failed	1

MOT #14	2024-03-21 16:15
MOT test number	951903874990
Result	✓ Passed
Next expiry date	2025-03-21
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #13**

2024-03-20 15:18

**MOT test number**

513147395868

**Result**

✗ Failed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #12**

2023-03-07 13:06

**MOT test number**

975522926357

**Result**

✓ Passed

**MOT #11**

2022-03-22 13:16

**MOT test number**

648859358770

**Result**

✓ Passed

**Advice** Under body covers fitted

**MOT #10**

2021-09-30 09:03

**MOT test number**

471657635198

**Result**

✓ Passed

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #9** 2021-09-30 09:03**MOT test number** 650448438787**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #8** 2020-09-16 06:39**MOT test number** 451244541501**Result** ✓ Passed**MOT #7** 2020-09-14 08:54**MOT test number** 401520235688**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Front Exhaust emissions likely to be affected by an exhaust leak FLEX PIPE (8.2.2.1 (b))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6** 2019-10-10 12:09**MOT test number** 957312520093**Result** ✓ Passed**MOT #5** 2018-10-03 16:24**MOT test number** 586692780087**Result** ✓ Passed**MOT #4** 2018-10-03 09:00**MOT test number** 120866248881**Result** ✗ Failed

**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**MOT #3** 2017-09-19 13:51**MOT test number** 378342097427**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2016-09-20 15:56**MOT test number** 658467460833**Result** ✓ Passed**MOT #1** 2015-09-18 07:59**MOT test number** 281895797363**Result** ✓ Passed

**Advice** Items removed from drivers view prior to test.

**Advice** Undertrays fitted obscuring some components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
21 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	21 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-20
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2012-09-20	11 mi
Registration #2	2015-09-18	20.426 mi
Registration #3	2016-09-20	30.457 mi
Registration #4	2017-09-19	43.587 mi
Registration #5	2018-10-03	55.282 mi
Registration #6	2018-10-03	55.284 mi
Registration #7	2019-10-10	64.378 mi
Registration #8	2020-09-14	67.841 mi
Registration #9	2020-09-16	67.841 mi
Registration #10	2020-09-20	67.841 mi
Registration #11	2020-09-20	67.841 mi
Registration #12	2020-09-20	67.841 mi
Registration #13	2020-09-20	67.841 mi
Registration #14	2020-09-20	67.841 mi
Registration #15	2020-09-20	67.841 mi
Registration #16	2020-09-20	67.841 mi
Registration #17	2020-09-20	67.841 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	A024J283