



General information

Make	VOLKSWAGEN
Model	TOUAREG TDI V10
Colour	Grey
Year of manufacture	2005
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	307 BHP
Max. torque	750 Nm at 2.000 rpm
Engine capacity	4.921 cc
Cylinders	10
Fuel type	Diesel
Consumption city	16.5 mpg
Consumption extra urban	28.8 mpg
Consumption combined	23.0 mpg
CO2 emission	332 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-08-26
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-12-12
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	19
Total items failed	0

MOT #15 2021-12-01 08:41

MOT test number 452333921743

Result ✓ Passed

Next expiry date 2022-12-12

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Direction indicator slightly discoloured both rear (4.4.3 (a))
- Advice** Under trays fitted

MOT #14 2020-11-13 14:56

MOT test number 169286553186

Result ✓ Passed

- Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))
- Advice** Oil leak
- Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement rearmost arm (5.3.4 (a) (i))
- Advice** Underbody shields fitted obscuring some testable components
- Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement rearmost arm (5.3.4 (a) (i))

**MOT #13** 2020-11-13 09:28**MOT test number** 554179467370**Result** ✗ Failed**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement rearmost arm (5.3.4 (a) (i))**Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**Advice** Underbody shields fitted obscuring some testable components**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement rearmost arm (5.3.4 (a) (i))**Advice** Oil leak**MOT #12** 2019-12-13 17:28**MOT test number** 328438954381**Result** ✓ Passed**MOT #11** 2019-02-14 17:44**MOT test number** 480357357824**Result** ✓ Passed**MOT #10** 2018-03-06 11:54**MOT test number** 736392437662**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Child Seat fitted not allowing full inspection of adult belt X 2**Advice** Offside Rear Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)



<b>MOT #9</b>	2017-01-26 14:50
---------------	------------------

<b>MOT test number</b>	761529567251
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2016-02-13 13:40
---------------	------------------

<b>MOT test number</b>	498927141689
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2015-01-17 13:54
---------------	------------------

<b>MOT test number</b>	969767915047
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Front Tyre worn close to the legal limit (4.1.E.1)
---------------	----------------------------------------------------

<b>MOT #6</b>	2013-11-02 13:38
---------------	------------------

<b>MOT test number</b>	669136603378
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-05-22 12:01
---------------	------------------

<b>MOT test number</b>	409033042184
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-05-13 13:10
---------------	------------------

<b>MOT test number</b>	566993731140
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-04-29 12:55
---------------	------------------

<b>MOT test number</b>	983339810134
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #2	2009-04-30 10:09
MOT test number	391110529193
Result	✓ Passed
MOT #1	2008-04-30 13:44
MOT test number	234081528409
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-05-06
Last registration	2021-12-01
Complete history	<a href="#">See info</a>



Registration #1	2005-05-06	27 mi
Registration #2	2008-04-30	36.494 mi
Registration #3	2009-04-30	47.641 mi
Registration #4	2010-04-29	54.790 mi
Registration #5	2011-05-13	62.980 mi
Registration #6	2012-05-22	69.103 mi
Registration #7	2013-11-02	75.238 mi
Registration #8	2015-01-17	80.616 mi
Registration #9	2016-02-13	84.472 mi
Registration #10	2016-02-13	84.472 mi
Registration #11	2016-02-13	84.472 mi
Registration #12	2016-02-13	84.472 mi
Registration #13	2016-02-13	84.472 mi
Registration #14	2016-02-13	84.472 mi
Registration #15	2016-02-13	84.472 mi
Registration #16	2016-02-13	84.472 mi
Registration #17	2016-02-13	84.472 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1940 mm
Height	1732 mm
Length	4795 mm
Wheel base	2893 mm
Kerb weight	2760 kg
Max. allowed weight	3100 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	AYH 016996