



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S AC
Colour	Blue
Year of manufacture	2012
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C







Internet history

Entry 2



Date	2021-07-10
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-10
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-10
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	25
Total items failed	11

MOT #14	2023-10-11 12:55
MOT test number	330245676868
Result	✓ Passed
Next expiry date	2024-10-10

MOT #13	2023-10-11 09:02
MOT test number	930446807759
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12	2022-06-30 11:22
MOT test number	439025234435
Result	✓ Passed

MOT #11	2021-07-22 06:56
MOT test number	933032655992
Result	✓ Passed
Advice	General underbody corrosion

**MOT #10**

2021-07-20 09:07

MOT test number

586762939012

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** General underbody corrosion
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #9

2020-10-29 11:07

MOT test number

654030997506

Result**✓ Passed****MOT #8**

2020-10-27 14:37

MOT test number

894283016140

Result**✗ Failed**

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded front to rear - above fuel tank (1.1.11 (c))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #7** 2019-04-11 15:46**MOT test number** 494895413364**Result** ✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear pipe (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6 2019-04-11 10:36**MOT test number** 276337873808**Result** ✗ Failed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear pipe (1.1.11 (c))

MOT #5 2018-04-10 08:32**MOT test number** 915842232314**Result** ✓ Passed

**MOT #4**

2017-04-19 09:19

MOT test number

515458583398

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened Lipped and corroded (3.5.1i)**Advice** Nearside Rear Tyre cracking with age**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre cracking with age**MOT #3**

2016-04-20 11:14

MOT test number

275056830039

Result

✓ Passed

Advice Both rear tyres are cracking in the tread**MOT #2**

2016-04-20 08:27

MOT test number

723327614335

Result

✗ Failed

Advice All tyres are cracking**Advice** Front wipers are poor**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #1**

2015-04-27 15:52

MOT test number

405327115154

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YG12FKT
Plate since	2019-03-28
Current registration	YG12FKT
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-30
Last registration	2023-10-11
Complete history	See info



Registration #1	2012-03-30	15 mi
Registration #2	2015-04-27	19.081 mi
Registration #3	2016-04-20	28.145 mi
Registration #4	2016-04-20	28.145 mi
Registration #5	2017-04-19	37.895 mi
Registration #6	2018-04-10	47.844 mi
Registration #7	2019-04-11	54.798 mi
Registration #8	2019-04-11	54.798 mi
Registration #9	2020-10-27	65.146 mi
Registration #10	2020-10-27	65.146 mi
Registration #11	2020-10-27	65.146 mi
Registration #12	2020-10-27	65.146 mi
Registration #13	2020-10-27	65.146 mi
Registration #14	2020-10-27	65.146 mi
Registration #15	2020-10-27	65.146 mi
Registration #16	2020-10-27	65.146 mi
Registration #17	2020-10-27	65.146 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1000 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1494752