





report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|--------------------|
| Model | CLIO DYNAMIQUE NAV |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 104 mph |
| 0 - 60 mph | 14.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 72 BHP |
|-------------------------|---------------------|
| Max. torque | 107 Nm at 4.250 rpm |
| Engine capacity | 1.149 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.2 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 1

| Date | 2021-05-21 | |
|---------------|--------------------|--|
| Pictures | 1 | |
| Listing price | <u>View report</u> | |



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-05-26 |
|--------------------|------------|
| MOT pass rate | 50 % |
| MOT passed | 3 |
| Failed MOT tests | 3 |
| Total advice items | 6 |
| Total items failed | 5 |

| MOT #6 | | 2023-05-23 12:48 |
|---|---|------------------|
| MOT test | number | 896263089726 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-05-26 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #5 | 2023-05-23 09:19 |
|---|------------------|
| MOT test number | 233164799046 |
| Result | X Failed |
| Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Rear Service brake excessively binding (1.2.1 (f)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2022-05-23 11:06 |
|-----------------|------------------|
| MOT test number | 901486651664 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



SC18HLA

report date: 2024-03-29

MOT test number

648210826616

Result

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #2
 2021-05-27 10:25

 MOT test number
 471100794991

 Result
 ✓ Passed

MOT #1 2021-05-24 13:16
MOT test number 421833569164

Result X Failed

Fail Offside Front Daytime running lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 247 |
| MOT expiry date | 26 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



SC18HLA

report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e union matery | |
|---|-------------|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Flate since | |
| Current registration | UK NEZ |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-06-29 |
| Last registration | 2023-05-23 |
| Complete history | See info |



| Registration #1 | 2018-06-29 | 12 mi |
|-----------------|------------|-----------|
| Registration #2 | | 11.777 es |
| Registration #3 | 2021-05-24 | 28.380 mi |
| Registration #4 | 2021-05-27 | 28.380 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | n |

More info >

page 10/11 CarCheck.co.uk



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 89% |
| Pedestrian | 66% |
| Safety systems | 99% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 1732 mm |
|---------------------|---------|
| Height | 1448 mm |
| Length | 4063 mm |
| Wheel base | 2589 mm |
| Kerb weight | 1059 kg |
| Max. allowed weight | 1564 kg |

Additional information

| Fuel tank capacity | 45 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number FC45511