





report date: 2024-03-28

#### General information

Make	KIA
Model	CARENS CRDI 4 ISG
Colour	Blue
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	58.9 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



## Internet history

E	n	t	r۱	,	2
E	n	τ	r٧	•	Z

Date	2021-12-16
Pictures	0
Listing price	View report

#### source: heycar.co.uk

#### Entry 1

Date	2021-12-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-16
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	20
Total items failed	0

MOT #10	2023-10-16 16:47
MOT test number	592441124158
Result	<b>✓</b> Passed
Next expiry date	2024-10-16

MOT #9		2023-10-16 12:01
MOT test number	er	327995930555
Result		<b>×</b> Failed
DANGEROUS	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #8		2022-10-17 07:56
MOT test n	umber	785476403299
Result		✓ Passed
Advice	Nearside Front Tyre is worn smooth on the inner and outer edges.	
Advice	Offside Front Tyre is worn smooth on the inner edge.	

CarCheck.co.uk page 3/12



MOT #7 2022-10-12 12:14

**MOT test number** 102682809679

Result X Failed

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**Advice** Offside Front Tyre is worn smooth on the inner edge.

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Nearside Front Tyre is worn smooth on the inner and outer edges.

**MOT #6** 2021-09-07 15:30

MOT test number 443562889328

**Result** 
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2021-09-07 14:44

**MOT test number** 589395443464

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MAJOR** Offside Obligatory mirror insecure (3.3 (b) (ii))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4 2020-09-01 14:55

**MOT test number** 912010878615

Result J Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))

CarCheck.co.uk page 4/12



MOT #3 2020-08-28 12:20

**MOT test number** 197525546758

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))

**DANGEROUS** Nearside Front Body component likely to become detached wheel arch liner (6.2.1 (a) (ii))

MOT #2 2019-09-06 14:48

**MOT test number** 778311119611

**Result** ✓ Passed

MOT #1 2019-09-06 11:33

**MOT test number** 530501606523

Result X Failed

**Advice** Offside Rear Nail in tyre

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	16 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
manus .	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-06-02
Last registration	2023-10-16
Complete history	See info



Registration #1	2016-06-02	21 mi
Registration #2	2019-09-06	32.639 mi
Registration #3	2019-09-06	32.643 mi
Registration #4	2020-08-28	45.298 mi
Registration #5	2020-09-01	45.298 mi
Registration #6	2021-09-07	57.482 mi
Registration #7	2021-09-07	57.482 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.000 au

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	76%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1724 kg
Max. allowed weight	2270 kg

# Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

**Engine number** D4FDFH543829