



SMIIOHJ

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 2


Date	2022-07-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2022-05-05
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #12 2023-07-05 10:22

MOT test number 473212048254

Result ✓ Passed

Next expiry date 2024-07-04

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2022-07-04 13:18

MOT test number 572261035562

Result ✓ Passed

MOT #10 2021-12-13 11:20

MOT test number 118383540094

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2020-12-18 09:47

MOT test number 924545458657

Result ✓ Passed

**MOT #8** 2019-06-21 11:21**MOT test number** 749340816507**Result** ✓ Passed**MOT #7** 2019-06-21 08:53**MOT test number** 501998136097**Result** ✗ Failed**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2018-06-04 12:19**MOT test number** 591598907625**Result** ✓ Passed**MOT #5** 2018-06-04 12:19**MOT test number** 458341814769**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2017-06-16 08:59**MOT test number** 876900507002**Result** ✓ Passed**MOT #3** 2016-06-09 10:59**MOT test number** 813412721319**Result** ✓ Passed**Advice** Nearside Rear has cuts to tyre**Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #2	2015-06-02 10:04
MOT test number	757233755145
Result	✓ Passed

MOT #1	2014-06-03 09:37
MOT test number	226494154483
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
4 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-30
Last registration	2023-07-05
Complete history	See info



Registration #1	2011-06-30	8 mi
Registration #2	2014-06-03	23.218 mi
Registration #3	2015-06-02	24.667 mi
Registration #4	2016-06-09	24.984 mi
Registration #5	2017-06-16	29.185 mi
Registration #6	2018-06-04	33.285 mi
Registration #7	2018-06-04	33.285 mi
Registration #8	2019-06-21	37.426 mi
Registration #9	2019-06-21	37.426 mi
Registration #10	2019-06-21	37.426 mi
Registration #11	2019-06-21	37.426 mi
Registration #12	2019-06-21	37.426 mi
Registration #13	2019-06-21	37.426 mi
Registration #14	2019-06-21	37.426 mi
Registration #15	2019-06-21	37.426 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A023I929