



report date: 2024-03-28

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Black
Year of manufacture	2004
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	420 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	33.6 mpg
Consumption combined	24.8 mpg
CO2 emission	279 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	44
Total items failed	9

MOT #27	2024-01-26 17:07
MOT test number	145881598821
Result	✓ Passed
Next expiry date	2025-01-25
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Rear Both rear drive shafts have end float in differential which gives the impression of play in the rear wheel bearings

MOT #26	2023-12-12 14:12
MOT test number	488603363894
Result	✗ Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Offside Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
MAJOR	Offside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
MAJOR	Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

**MOT #25**

2022-11-22 16:42

MOT test number

360465653224

Result

✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Some Play At Both Rear Inner Drive Shaft Attachment's

MOT #24

2022-11-18 14:46

MOT test number

531955685443

Result

✗ Failed

- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Nearside Brake pipe excessively corroded Central (1.1.11 (c))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- DANGEROUS** Stop lamp(s) remains on when the brakes are released All (4.3.2 (a) (iii))
- Advice** Some Play At Both Rear Inner Drive Shaft Attachment's
- MAJOR** Offside Brake pipe excessively corroded Central (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #23

2021-11-16 10:07

MOT test number

653572724179

Result

✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))



MOT #22	2020-11-19 12:22
---------	------------------

MOT test number	439935098565
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #21	2019-06-08 11:56
---------	------------------

MOT test number	372552969107
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #20	2018-09-14 06:57
---------	------------------

MOT test number	353306501527
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #19	2018-09-13 08:18
---------	------------------

MOT test number	498464943940
-----------------	--------------

Result	✗ Failed
--------	----------

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #18	2017-09-11 14:36
---------	------------------

MOT test number	539554755819
-----------------	--------------

Result	✓ Passed
--------	----------

Advice Nearside front tyre slight damage to outer sidewall.

Advice Both front tyres worn inner edges.

MOT #17	2016-09-05 12:04
---------	------------------

MOT test number	484192054610
-----------------	--------------

Result	✓ Passed
--------	----------

**MOT #16** 2016-09-02 09:27**MOT test number** 515339704407**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Nail in tyre**Advice** Brakes should be checked/serviced.**Fail** Nearside Front Lower Shock absorber has an excessively worn bush (2.7.4)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #15** 2015-08-14 08:49**MOT test number** 151781548491**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2014-08-20 12:42**MOT test number** 335742334277**Result** ✓ Passed**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2013-08-22 11:34**MOT test number** 975994133264**Result** ✓ Passed

**MOT #12** 2013-08-20 13:09**MOT test number** 886032333246**Result** ✗ Failed**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2012-08-24 15:51**MOT test number** 707137832242**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Windscreen stone chipped**MOT #10** 2012-08-22 16:29**MOT test number** 295145832227**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Oil leak**Advice** Offside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Windscreen stone chipped**Advice** Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #9** 2011-08-16 17:09**MOT test number** 809048521272**Result** ✓ Passed

**MOT #8** 2011-08-16 15:27**MOT test number** 746768221207**Result** ✗ Failed**Fail** Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2010-08-26 09:05**MOT test number** 864968730225**Result** ✓ Passed**Notice** Windscreen stone chipped**MOT #6** 2010-08-23 16:45**MOT test number** 991565330245**Result** ✗ Failed**Notice** High level brake light not working**Notice** Windscreen stone chipped**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #5** 2009-07-30 13:06**MOT test number** 271431219220**Result** ✓ Passed**MOT #4** 2008-08-21 14:27**MOT test number** 253024938206**Result** ✓ Passed**MOT #3** 2007-09-18 12:20**MOT test number** 704821567268**Result** ✓ Passed



MOT #2	2007-09-18 12:00
MOT test number	880381467274
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2007-04-17 12:46
MOT test number	320737307110
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2004-04-22
Last registration	2024-01-26
Complete history	See info



Registration #1	2004-04-22	10 mi
Registration #2	2007-04-17	29.441 mi
Registration #3	2007-09-18	30.178 mi
Registration #4	2007-09-18	30.178 mi
Registration #5	2008-08-21	36.257 mi
Registration #6	2009-07-30	41.667 mi
Registration #7	2010-08-23	46.648 mi
Registration #8	2010-08-26	46.648 mi
Registration #9	2011-08-16	52.622 mi
Registration #10	2011-08-16	52.622 mi
Registration #11	2012-08-22	57.065 mi
Registration #12	2012-08-24	57.069 mi
Registration #13	2013-08-20	61.378 mi
Registration #14	2013-08-22	61.378 mi
Registration #15	2014-08-20	66.649 mi
Registration #16	2015-08-20	71.920 mi
Registration #17	2016-08-20	77.191 mi
Registration #18	2017-08-20	82.462 mi
Registration #19	2018-08-20	87.733 mi
Registration #20	2019-08-20	93.004 mi
Registration #21	2020-08-20	98.275 mi
Registration #22	2021-08-20	103.546 mi
Registration #23	2022-08-20	108.817 mi
Registration #24	2023-08-20	114.088 mi
Registration #25	2024-01-26	119.359 mi
Registration #26	2024-01-26	119.359 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Dimensions & weight

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm
Kerb weight	1685 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	2B0312031537