



Mercedes-Benz

**BRZIO48**

report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	2007
Top speed	144 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-11-09
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-08-02
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	41
Total items failed	20

MOT #18	2023-08-03 14:46
MOT test number	365115730661
Result	✓ Passed
Next expiry date	2024-08-02

MOT #17	2022-03-08 12:10
MOT test number	179207694089
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2020-11-30 15:49
MOT test number	650901458792
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output Both sides (4.1.4 (b))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Vehicle Undertrays fitted obscuring view to underside
Advice	Front Play in steering rack inner joint(s) Both sides
Advice	Rear Brake hose slightly deteriorated Both sides (1.1.12 (b) (ii))

**MOT #15**

2020-11-11 15:50

MOT test number

775634057187

Result

✗ Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside headlamp lens deteriorated

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Nearside Front fog lens cracked

Fail Exhaust has a major leak of exhaust gases cat cracked (6.1.2 (a))

Advice Nearside Play in steering rack inner joint(s)

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside headlamp lens deteriorated

Advice Offside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity taped (4.2.3 (b) (ii))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #14

2019-10-29 16:25

MOT test number

137778816644

Result

✓ Passed

MOT #13

2018-11-06 14:55

MOT test number

250358664108

Result

✓ Passed

**MOT #12**

2017-11-09 09:53

MOT test number

134399886722

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Both headlight reflectors corroding**MOT #11**

2017-11-01 10:11

MOT test number

678495792252

Result

✗ Failed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Nail in tyre**Advice** Both headlight reflectors corroding**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #10**

2016-11-02 13:41

MOT test number

566359653202

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2016-11-02 12:11**MOT test number** 809245616797**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Centre Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2015-10-27 12:23**MOT test number** 547234348543**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-10-27 09:21**MOT test number** 724220364734**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Rear Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #6** 2015-10-23 13:45**MOT test number** 886209254190**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Front Tyre worn close to the legal limit both sides (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Service brake: efficiency below requirements (3.7.B.7)**MOT #5** 2014-10-17 15:30**MOT test number** 929840994233**Result** ✓ Passed**MOT #4** 2013-04-13 11:24**MOT test number** 766543503179**Result** ✓ Passed**MOT #3** 2012-04-10 17:54**MOT test number** 497571502132**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-03-24 19:01
MOT test number	398763781097
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-03-29 16:17
MOT test number	261898380067
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 BRZ1048
Plate since	2024-03-29
Current registration	 BRZ1048
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-30
Last registration	2023-08-03
Complete history	See info



Registration #1	2007-03-30	22 mi
Registration #2	2010-03-29	36.985 mi
Registration #3	2011-03-24	38.830 mi
Registration #4	2012-04-10	41.381 mi
Registration #5	2013-04-13	49.768 mi
Registration #6	2014-10-17	62.418 mi
Registration #7	2015-10-23	67.423 mi
Registration #8	2015-10-27	67.456 mi
Registration #9	2015-10-27	67.456 mi
Registration #10	2016-11-02	73.750 mi
Registration #11	2016-11-02	73.750 mi
Registration #12	2016-11-02	73.750 mi
Registration #13	2016-11-02	73.750 mi
Registration #14	2016-11-02	73.750 mi
Registration #15	2016-11-02	73.750 mi
Registration #16	2016-11-02	73.750 mi
Registration #17	2016-11-02	73.750 mi
Registration #18	2016-11-02	73.750 mi
Registration #19	2016-11-02	73.750 mi
Registration #20	2016-11-02	73.750 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530879858