



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Red
Year of manufacture	2008
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-08
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-09
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #15	2024-01-10 17:26
MOT test number	209767366569
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14	2022-12-08 18:02
MOT test number	940842230620
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))

MOT #13	2021-10-28 16:56
MOT test number	768301652149
Result	✓ Passed
Advice	Power steering ram has slight seepage from a joint (2.1.5 (a))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12** 2020-10-26 14:06**MOT test number** 154522743890**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central non obligatory mirror missing
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2020-10-26 10:05**MOT test number** 744970757787**Result** ✗ Failed

- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central non obligatory mirror missing
- Fail** Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2019-10-07 12:23**MOT test number** 353556642144**Result** ✓ Passed**MOT #9** 2018-10-25 10:36**MOT test number** 310267904855**Result** ✓ Passed

**MOT #8** 2018-10-25 08:52**MOT test number** 793835418714**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #7** 2017-10-30 10:31**MOT test number** 849102016122**Result** ✓ Passed**MOT #6** 2016-09-01 12:08**MOT test number** 648307362607**Result** ✓ Passed**Advice** Front tyres worn on edges**MOT #5** 2015-08-19 13:19**MOT test number** 831892444232**Result** ✓ Passed**Advice** O/s & n/s front tyres deteriorated**MOT #4** 2014-08-28 13:55**MOT test number** 937100744289**Result** ✓ Passed**MOT #3** 2013-08-22 14:17**MOT test number** 148374733295**Result** ✓ Passed



MOT #2	2012-08-16 14:23
MOT test number	367639322212
Result	✓ Passed

MOT #1	2011-08-30 13:56
MOT test number	459002141237
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-01
Last registration	2024-01-10
Complete history	See info



Registration #1	2008-09-01	22 mi
Registration #2	2011-08-30	7.091 mi
Registration #3	2012-08-16	8.985 mi
Registration #4	2013-08-22	10.880 mi
Registration #5	2014-08-28	12.613 mi
Registration #6	2015-08-19	14.111 mi
Registration #7	2016-09-01	16.739 mi
Registration #8	2017-10-30	29.501 mi
Registration #9	2018-05-20	35.377 mi
Registration #10	2019-05-20	35.377 mi
Registration #11	2020-05-20	35.377 mi
Registration #12	2021-05-20	35.377 mi
Registration #13	2022-05-20	35.377 mi
Registration #14	2023-05-20	35.377 mi
Registration #15	2024-01-10	35.377 mi
Registration #16	2024-01-10	35.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG8476034